

# **Vehicle History Report**

#### **VEHICLE DETAILS**

Chassis number <sup>1</sup> :	RG1-1360279	Title information <sup>2</sup> :	, C	Deregistered to Export	<b>Ø</b>
Manufacture date:	2009-08-31	Accident / Repair:	Ĭ <del>=</del>	No problem	•
Make:	HONDA	Odometer rollback:		No problem	•
Model:	STEPWGN	Manufacturer			
Body:	DBA-RG1	recall:	٧	No problem	<b>S</b>
Grade:	SPADA S Z HDD NAVI PACKAGE	Safety grade <sup>3</sup> :	8	****	<b>②</b>
Engine:	K20A	Contamination risk:		No problem	•
Drive:	2WD				
Transmission:	AT				

#### This vehicle does not qualify for Buyback Guarantee

**Average Market Price** 



Unfortunately, this vehicle does not qualify for our Buyback Guarantee program.





About Buyback Guarantee

This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2024-03-07 01:13:04. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### **ACCIDENT / REPAIR HISTORY**

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

## **ODOMETER READINGS HISTORY**

Date reported	Data source	Odometer reading (Km)
2020-09-07	MLIT	96200
2022-09-06	MLIT	106900
2023-11-14	JU Saitama	113953

## **USE HISTORY**

Use in the contaminated regions <sup>4</sup> Radioactive contamination test fail <sup>5</sup> Commercial use

Not reported

Not reported

Not reported

## **DETAILED HISTORY**

Event date	Location	Odometer reading (Km)	Data source	Details
2009-08-31			HONDA	Manufactured
2009-09			MLIT	First registration
2020-09-07		96200	MLIT	Inspection
2022-09-06	Kasukabe	106900	MLIT	Inspection
2023-10-30	Kasukabe		MLIT	Last registration

2023-11-14 Saitama 113953 JU Saitama Auctioned

### **MANUFACTURER RECALL HISTORY**

Date reported Data source Affected part **Details** 



Not reported

#### **VEHICLE ASSESSMENT** 6

#### **Overall Collision Safety Ratings**

Driver's seat			Front passenger's seat		
Points	Evaluation	Goal average	Points	Evaluation	Goal average
34.68	****	96%	22.89	****	95%

<sup>\*</sup> In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

#### Braking performance tests 7



#### **VEHICLE SPECIFICATION**

1st gear ratio	2.684	2nd gear ratio	1.534
3rd gear ratio	1.081	4th gear ratio	0.695
5th gear ratio	-	6th gear ratio	-
Additional notes	-	Airbag position, capacity	-
Body rear overhang	890	Body type	MV&1BOX

Chassis number embossing position	BONNET INSIDE DASH BOARD UPPER FRONT SURFACE	Classification code	0297
Cylinders	4 WIDTH	Displacement	1990
Electric engine type	-	Electric engine maximum output	-
Electric engine maximum torque	-	Electric engine power	-
Engine maximum power	114/6000( NET)	Engine maximum torque	188/4500( NET)
Engine model	K20A	Frame type	SOLID STRUCTURE
Front shaft weight	910	Front shock absorber type	
Front stabilizer type	TORSION · BAR TYPE	Front tires size	205/60R16 92H
Front tread	1470	Fuel consumption	12.2
Fuel tank equipment	57	Grade	SPADA S Z HDD NAVI PACKAGE
Height	1770	Length	4660
Main brakes type	HYDRAULIC TYPE DISK HYDRAULIC TYPE DISK	Make	HONDA
Maximum speed	170	Minimum ground clearance	155
Minimum turning radius	5.3	Model	STEPWGN
Model code	DBA-RG1	Mufflers number	
Rear shaft weight	650	Rear shock absorber type	
Rear stabilizer type	TORSION · BAR TYPE	Rear tires size	205/60R16 92H
Rear tread	1460	Reverse ratio	2.000
Riding capacity	8	Side brakes type	MACHINE CAR WHEEL SHAPE( DRUM TYPE)
Specification code	15065	Stopping distance	53(100)
Transmission type	AT	Weight	1560
Wheel alignment	2WD	Wheelbase	2855

Width

1695


## **AUCTION DATA**

Date: 2023-11-14, Auction: JU Saitama, Lot #: 3125

Date:	2023-11-14	Lot #:	3125
Auction name:	JU Saitama	Region:	Saitama
Make:	HONDA	Model:	STEPWGN SPADA
Reg. year:	2009	Mileage (km):	113953
Displacement (cc):	2000	Transmission:	IA
Color:	BLACK	Model code:	RG1
Result:	sold	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

## **PHOTOS AND AUCTION SHEETS**

# ★ディーラー出品★初出品★









#### **GLOSSARY**

<sup>1</sup> Chassis number – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

#### <sup>2</sup> Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

<sup>3</sup> Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

- <sup>4</sup> Use in the contaminated regions The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.
- <sup>5</sup> Radioactive contamination test radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT - Ministry of Land, Infrastructure, Transport and Tourism.

- <sup>6</sup> Japan New Car Assessment Program the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.
- <sup>7</sup> Braking Performance Tests Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2024 Car VX Limited. All rights reserved.