



# Vehicle History Report

## VEHICLE DETAILS

**Chassis number <sup>1</sup>:** PE52-050743

**Manufacture date:** 2014-02

**Make:** NISSAN

**Model:** ELGRAND

**Body:** DBA-PE52

**Grade:** 350 HIGHWAY STAR

**Engine:** VQ35DE

**Drive:** 2WD

**Transmission:** AT

**Title information <sup>2</sup>:**



**Deregistered to Export**



**Accident / Repair:**



**No problem**



**Odometer rollback:**



**No problem**



**Manufacturer recall:**



**No problem**



**Safety grade <sup>3</sup>:**



★★★★★★



**Contamination risk:**









**No problem**



This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2025-06-13 16:13:15. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD . Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.




ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	 Not reported				
Malfunction	 Not reported				
Theft	 Not reported				
Fire damage	 Not reported				
Water damage	 Not reported				
Hail damage	 Not reported				

ODOMETER READINGS HISTORY

Date reported	Data source	Odometer reading (Km)
2021-02-22	MLIT	37900
2023-02-09	MLIT	46700
2025-05-10	USS Kyushu	54000

USE HISTORY

Use in the contaminated regions <sup>4</sup>	Radioactive contamination test fail <sup>5</sup>	Commercial use
 Not reported	 Not reported	 Not reported

DETAILED HISTORY

Event date	Location	Odometer reading (Km)	Data source	Details
2014-02			NISSAN	Manufactured
2014-02			MLIT	First registration
2021-02-22		37900	MLIT	Inspection
2023-02-09	Fukuoka	46700	MLIT	Inspection
2025-02-26	Fukuoka		MLIT	Last registration

MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
---------------	-------------	---------------	---------

Not reported



VEHICLE ASSESSMENT <sup>6</sup>

Overall Collision Safety Ratings

Driver's seat			Front passenger's seat		
Points	Evaluation	Goal average	Points	Evaluation	Goal average
35.37	★★★★★	98%	23.33	★★★★★	97%

\* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

Braking performance tests <sup>7</sup>

Dry road		40.5 m
Wet road		43.4 m

VEHICLE SPECIFICATION

1st gear ratio	2nd gear ratio	
3rd gear ratio	4th gear ratio	
5th gear ratio	6th gear ratio	
Additional notes	Airbag position, capacity	
Body rear overhang	Body type	MV&1BOX

Chassis number embossing position		Classification code	227
Cylinders		Displacement	3490
Electric engine type		Electric engine maximum output	
Electric engine maximum torque		Electric engine power	
Engine maximum power	280ps(206kW) / 6400rpm	Engine maximum torque	35.1kg· m(344N· m) / 4400rpm
Engine model	VQ35DE	Frame type	
Front shaft weight	1100	Front shock absorber type	
Front stabilizer type		Front tires size	225/55R18 98V
Front tread	1600	Fuel consumption	
Fuel tank equipment	73	Grade	350 HIGHWAY STAR
Height	181	Length	494
Main brakes type		Make	NISSAN
Maximum speed		Minimum ground clearance	
Minimum turning radius	5.7	Model	ELGRAND
Model code	DBA-PE52	Mufflers number	
Rear shaft weight	920	Rear shock absorber type	
Rear stabilizer type		Rear tires size	225/55R18 98V
Rear tread	1600	Reverse ratio	
Riding capacity	7	Side brakes type	
Specification code	16578	Stopping distance	
Transmission type	AT	Weight	2020
Wheel alignment	2WD	Wheelbase	3000
Width	185		

Date: 2025-05-10, Auction: USS Kyushu, Lot #: 20031

Date:	2025-05-10	Lot #:	20031
Auction name:	<a href="#">USS Kyushu</a>	Region:	Saga
Make:	NISSAN	Model:	ELGRAND
Reg. year:	2014	Mileage (km):	54000
Displacement (cc):	3500	Transmission:	AT
Color:	BLACK	Model code:	PE52
Result:	available	Auction grade:	4.5
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

PHOTOS AND AUCTION SHEETS

## スライドドアコーナー

20031	車種 (商標名以外は記入)	排気量	型式	評価点
	26/3月	2500	ABA-PE52	4.5
	初年度登録年月	車名	グレード	4WD
	26/3月	インテグリティ	5速	B

車種	年	月	シフト	AT	SR	MAN	BOX	PC
走行	58,000	km	冷間	AAC	セルスロイント			
外色	白色	カラー	有・無		★純正エアー・70.70cm TV			
内色	70	GAE	★純正アクト・210					
国産	カブ・新車		★純正1817マフ・エクスト					
型式		ハンドル	★バブ・1817					
ディーラー・銀行	左・右		★純正1817					
リサイクル	18740	円						
注意事項	(説明・写真・書類あり)							

トヨタ  
ハイエース

図1

図2

図3

図4

図5

図6

図7

図8

図9

図10

図11

図12

図13

図14

図15

図16

図17

図18

図19

図20

図21

図22

図23

図24

図25

図26

図27

図28

図29

図30

図31

図32

図33

図34

図35

図36

図37

図38

図39

図40

図41

図42

図43

図44

図45

図46

図47

図48

図49

図50

図51

図52

図53

図54

図55

図56

図57

図58

図59

図60

図61

図62

図63

図64

図65

図66

図67

図68

図69

図70

図71

図72

図73

図74

図75

図76

図77

図78

図79

図80

図81

図82

図83

図84

図85

図86

図87

図88

図89

図90

図91

図92

図93

図94

図95

図96

図97

図98

図99

図100

図101

図102

図103

図104

図105

図106

図107

図108

図109

図110

図111

図112

図113

図114

図115

図116

図117

図118

図119

図120

図121

図122

図123

図124

図125

図126

図127

図128

図129

図130

図131

図132

図133

図134

図135

図136

図137

図138

図139

図140

図141

図142

図143

図144

図145

図146

図147

図148

図149

図150

図151

図152

図153

図154

図155

図156

図157

図158

図159

図160

図161

図162

図163

図164

図165

図166

図167

図168

図169

図170

図171

図172

図173

図174

図175

図176

図177

図178

図179

図180

図181

図182

図183

図184

図185

図186

図187

図188

図189

図190

図191

図192

図193

図194

図195

図196

図197

図198

図199

図200

図201

図202

図203

図204

図205

図206

図207

図208

図209

図210

図211

図212

図213

図214

図215

図216

図217

図218

図219

図220

図221

図222

図223

図224

図225

図226

図227

図228

図229

図230

図231

図232

図233

図234

図235

図236

図237

図238

図239

図240

図241

図242

図243

図244

図245

図246

図247

図248

図249

図250

図251

図252

図253

図254

図255

図256

図257

図258

図259

図260

図261

図262

図263

図264

図265

図266

図267

図268

図269

図270

図271

図272

図273

図274

図275

図276

図277

図278

図279

図280

図281

図282

図283

図284

図285

図286

図287

図288

図289

図290

図291

図292

図293

図294

図295

図296

図297

図298

図299

図300

図301

図302

図303

図304

図305

図306

図307

図308

図309

図310

図311

図312

図313

図314

図315

図316

図317

図318

図319

図320

図321

図322

図323

図324

図325

図326

図327

図328

図329

図330

図331

図332

図333

図334

図335

図336

図337

図338

図339

図340

図341

図342

図343

図344

図345

図346

図347

図348

図349

図350

図351

図352

図353

図354

図355

図356

図357

図358

図359

図360

図361

図362

図363

図364

図365

図366

図367

図368

図369

図370

図371

図372

図373

図374

図375

図376

図377

図378

図379

図380

図381

図382

図383

図384

図385

図386

図387

図388

図389

図390

図391

図392

図393

図394

図395

図396

図397

図398

図399

図400

図401

図402

図403

図404

図405

図406

図407

図408

図409

図410

図411

図412

図413

図414

図415

図416

図417

図418

図419

図420

図421

図422

図423

図424

図425

図426

図427

図428

図429

図430

図431

図432

図433

図434

図435

図436

図437

図438

図439

図440

図441

図442

図443

図444

図445

図446

図447

図448

図449

図450

図451

図452

図453

図454

図455

図456

図457

図458

図459

図460

図461

図462

図463

図464

図465

図466</

**<sup>1</sup> Chassis number** – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

**<sup>2</sup> Title information:**

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped

Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

**<sup>3</sup> Determining the overall collision safety performance evaluation** – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

**<sup>4</sup> Use in the contaminated regions** – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

**<sup>5</sup> Radioactive contamination test** – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

**<sup>6</sup> Japan New Car Assessment Program** – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

**<sup>7</sup> Braking Performance Tests** – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2025 Car VX Limited. All rights reserved.