

# **Vehicle History Report**

#### **VEHICLE DETAILS**

Chassis number 1: NGC30-0009904 Manufacture date: 2010-09 Make: **TOYOTA PASSO** Model: DBA-NGC30 Body: Grade: 1.3 + HANA **Engine:** 1NR Drive: 2WD Transmission: AΤ

Deregistered to Title information <sup>2</sup>: **Export Accident / Repair:** No problem Odometer No problem rollback: Manufacturer No problem recall: Safety grade <sup>3</sup>: \*\*\*\*\* Contamination No problem risk:

#### This vehicle does not qualify for Buyback Guarantee

**Average Market Price** 



Unfortunately, this vehicle does not qualify for our Buyback Guarantee program.



¥320,000

**About Buyback Guarantee** 

This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2023-06-08 20:34:25. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

## **ACCIDENT / REPAIR HISTORY**

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

## **ODOMETER READINGS HISTORY**

Date reported	Data source	Odometer reading (Km)
2019-08-20	MLIT	25300
2021-08-24	MLIT	28400
2022-05-12	MIRIVE Osaka	29234
2022-10-19	JAA HAA	29240
2023-05-31	CAA Chubu	33501

## **USE HISTORY**

Use in the contaminated regions <sup>4</sup>	Radioactive contamination test fail <sup>5</sup>	Commercial use
Not reported	Not reported	Not reported

## DETAILED HISTORY

Event date	Location	Odometer reading (Km)	Data source	Details
2010-09			TOYOTA	Manufactured
2010-09			MLIT	First registration
2019-08-20		25300	MLIT	Inspection

2021-08-24	Yokohama	28400	MLIT	Inspection
2022-05-12	Osaka	29234	MIRIVE Osaka	Auctioned
2022-10-19		29240	JAA HAA	Auctioned
2023-05-31	Aichi	33501	CAA Chubu	Auctioned
2023-06-06	Yokohama		MLIT	Last registration

#### **MANUFACTURER RECALL HISTORY**

Date reported	Data source	Affected part	Details
Not reported			

#### VEHICLE ASSESSMENT 6

#### **Overall Collision Safety Ratings**

Driver's seat			Front passeng	er's seat	
Points	Evaluation	Goal average	Points	Evaluation	Goal average
32.37	****	90%	21.74	*****	91%

<sup>\*</sup> In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

### Braking performance tests 7



#### **VEHICLE SPECIFICATION**

1st gear ratio	2.386 ~ 0.426: CONTINUOUSLY VARIABLE TRANSMISSION	2nd gear ratio	-
3rd gear ratio	-	4th gear ratio	-

5th gear ratio	-	6th gear ratio	-
Additional notes	AHEFK	Airbag position, capacity	-
Body rear overhang	515	Body type	BOX TYPE
Chassis number embossing position	ENGINE ROOM TOOL INSIDE COWL PANEL CENTRE ATTACHING CLOSE	Classification code	0002
Cylinders	4	Displacement	1320
Electric engine type	-	Electric engine maximum output	-
Electric engine maximum torque	-	Electric engine power	-
Engine maximum power	70/6000( NET)	Engine maximum torque	121/4000( NET)
Engine model	1NR	Frame type	SOLID STRUCTURE
Front shaft weight	600	Front shock absorber type	
Front stabilizer type	-	Front tires size	155/80R13 79S 165/70R14 81S
Front tread	1.465 1.455	Fuel consumption	21.0
Fuel tank equipment	40	Grade	1.3 + HANA
Height	1.535	Length	3.650
Main brakes type	HYDRAULIC TYPE, FRONT DISK BACK LEADING TRAILING	Make	ТОУОТА
Maximum speed	170	Minimum ground clearance	0.140
Minimum turning radius	4.3 4.7	Model	PASSO
Model code	DBA-NGC30	Mufflers number	
Rear shaft weight	340	Rear shock absorber type	

Rear stabilizer type	-	Rear tires size	155/80R13 79S 165/70R14 81S
Rear tread	1.475 1.465	Reverse ratio	2.505
Riding capacity	5	Side brakes type	MACHINE CAR WHEEL制動 SHAPE( DRUM TYPE)
Specification code	16442	Stopping distance	65(100)
Transmission type	AT	Weight	940
Wheel alignment	2WD	Wheelbase	2.440
Width	1.665		

## **AUCTION DATA**

Date: 2022-05-12, Auction: MIRIVE Osaka, Lot #: 10049

Date:	2022-05-12	Lot #:	10049
Auction name:	MIRIVE Osaka	Region:	Osaka
Make:	ТОУОТА	Model:	PASSO
Reg. year:	2010	Mileage (km):	29234
Displacement (cc):	1300	Transmission:	AT
Color:	GREEN	Model code:	NGC30
Result:	sold	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

Date: 2022-10-19, Auction: JAA HAA, Lot #: 72377


Date:	2022-10-19	Lot #:	72377
Auction name:	JAA HAA	Region:	
Make:	TOYOTA	Model:	PASSO
Reg. year:	2010	Mileage (km):	29240
Displacement (cc):	1300	Transmission:	CAT
Color:	CHAIR METALLIC	Model code:	NGC30

Result:	available	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

Date: 2023-05-31, Auction: CAA Chubu, Lot #: 36295

Date:	2023-05-31	Lot #:	36295
Auction name:	CAA Chubu	Region:	Aichi
Make:	TOYOTA	Model:	PASSO
Reg. year:	2010	Mileage (km):	33501
Displacement (cc):	1300	Transmission:	CAT
Color:	GREEN	Model code:	NGC30
Result:	sold	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	ОК

## PHOTOS AND AUCTION SHEETS


















初年度登録	у- <i>-</i> р-	<u>ーーー</u> ヨタ	ドア枚数	5	ボディ形状	h L	ハッチ	バック	<b>評価点</b>
H22/9я	車名 / (*	ッソ	<sub>グレード</sub> プラ		920	717		型制区分 2WD 4WD	4
車 自御用 ・その他(	拼 気 量	1300 cc 型式	NO	iC30	通* 型 5	t		内装 A	·B· c
<b>東</b> 5 <sub>年</sub> 9	月/ 抹消	燃 メンシ 料 ハイブリッド (	ディーゼル	<u> </u>	後日送り	16 ( f	果証書・	取扱説明書 等	<b>\$</b> )
	*:改ぎん #:不明) 百 + - 2 4 0 優	ーコラム	ΑТ						
<sup>外装色</sup> ウグイスメタリック	カラーNo.	AC · QAC · WAC	•( )		藝	<b>常品</b> 6	DA O	印 を記入	10
色養率は()内に 「色養」と記入	内装色	乗車定員	5 A	Ø	Ø	•	(A)	サンルーフ	革シート
た ・ (海 な) ディーラー	・ 並行	イラル料 9,420	円 ・ 預託 <b>弁</b>	# ±Ø	77 B	à	ナビ	TV	<b>₩</b> 2
				A1U 停復服				A1	2-57
検査記入欄			Δ	有 . (	U 스크로·オサ	L B I±	ズ・ヘユミ	P 色あせ・ポケ	G ガラスキズ
ドアミラーPアセ 下廻り	S		w	補條款	S ##	С		X 交換要	XX 交換府
ホイルCPキズ ドアミラーキズ			丑藓	No		月		日まで	名変中に名変できる方
小キズ有小U有 コアサポート✕&#	10005; (ネジ)	ř	車	* NG	C30-000		4	, ,	
PW (H2)5 186A 71	А .	*/" I	アロ シリフ ・ワレ Na						
内装 (31) ½ Y7	1 1	コゲ穴 オーディオ穴	150-20	長さ	cm #		高さ cm	最大	教教量 Kg



# / オクステージ





A:42~U:A:2 B:42~を伴うA:3 P:要塗装 W:補修跡 S:鎬 C:腐食、穴 G:7my h\*5ス点42~XX:交換済み X:要交換 欠:欠品 内・外装評価 5段階599順(A・B・C・D・E) 1
























#### **GLOSSARY**

<sup>1</sup> Chassis number – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

#### <sup>2</sup> Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

<sup>3</sup> Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

- <sup>4</sup> Use in the contaminated regions The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.
- <sup>5</sup> Radioactive contamination test radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT - Ministry of Land, Infrastructure, Transport and Tourism.

- <sup>6</sup> Japan New Car Assessment Program the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.
- <sup>7</sup> Braking Performance Tests Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2023 Car VX Limited. All rights reserved.