

Recall Check

VIN / Chassis ANH25-8022889
Make Toyota
Source Toyota, https://toyota.jp/recall/2017/0330_3.html
Check date 12/10/2026
Result No outstanding recalls – all completed

Recall / campaign	What it was	Type	Date filed	Status
Takata airbag recall	Passenger airbag inflator propellant may degrade with heat and humidity, so the inflator could rupture on deployment – inflator or airbag assembly replaced	Recall	30/03/2017	Completed

The original Japanese result page from the manufacturer follows.

該当するリコール等の内容と実施状況の検索結果

入力された車台番号 【ANH25-8022889】

【検索結果】

ご入力いただいたおクルマについて該当するリコール等の内容および実施状況は以下のとおりです。

No.		内容	届出日（開始日）	実施状況
1		タカタ製エアバッグのリコールについて 	2017年03月30日届出	実施済

ご愛用の皆様には大変ご迷惑をおかけしましたことを心からお詫び申し上げます。

「未実施」の項目があるお客様には、お手数をお掛けして誠に申し訳ございませんが、お早めに、販売店へご来店日時をご相談いただき、修理をお受けいただきますよう、お願い申し上げます。

ご不明な点などありましたら、お近くの販売店または、下記のお客様相談センターへお問い合わせください。

お近くの販売店がおわかりにならない場合は、[「販売店検索」](#)  機能でご確認をお願いします。

【ご注意】

*リコール・改善対策は1999年1月以降の情報から、サービスキャンペーンは2002年1月以降の情報から検索いたしました。

*リコール、改善対策、サービスキャンペーンの修理作業実施後、検索結果に反映されるのに2週間以上かかる場合があります。

*実施状況は日本国内における修理の実施状況を表示したものです。

続けて検索される場合は車台番号を入力し、「検索」ボタンを押してください。

車台番号

-

検索 ▶

(半角英数字)

(半角英数字)

例：

ABC123

-

1234567

お問い合わせ先

自動車検査証(車検証)をご用意いただくとスムーズな対応が可能です。

トヨタ自動車株式会社 お客様相談センター

フリーコール 0800-700-7700
0800-700-7700
受付日 9:00～17:00（長期連休などの当
時： 社指定日を除く）

レクサスインフォメーションデスク

フリーコール 0800-500-5577
0800-500-5577
受付日 9:00～17:00（長期連休などの当
時： 社指定日を除く）

リコール情報

対象車両検索

タカタ製エアバッグリコール