

## Recall Check

**VIN / Chassis** GP8-1004454  
**Make** Honda  
**Source** Honda, [https://www.honda.co.jp/recall/auto/campaign/201127\\_KC32.html](https://www.honda.co.jp/recall/auto/campaign/201127_KC32.html)  
[https://www.honda.co.jp/recall/auto/campaign/190726\\_KC28.html](https://www.honda.co.jp/recall/auto/campaign/190726_KC28.html)  
**Check date** 12/10/2026  
**Result** **No outstanding recalls – all completed**

| Recall / campaign                | What it was                                                                                                                                               | Type             | Date filed | Status    |
|----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|------------|-----------|
| Start/stop switch replacement    | Engine start/stop (power) switch contacts may lose conductivity, lighting a warning lamp – switch replaced                                                | Service campaign | 27/11/2020 | Completed |
| TDU / PGM-FI ECU software update | DCT gearbox control program may fail to engage 1st gear after a worn hub, showing a warning and preventing pull-away – transmission computer reprogrammed | Service campaign | 26/07/2019 | Completed |

The original Japanese result page from the manufacturer follows.

4輪 リコール・改善対策・サービスキャンペーン 対象車両検索

入力された車台番号 GP8-1004454

お客様が入力された車台番号のおクルマは、リコール等がすべて実施済みです。  
安心してお使いいただけます。

【検索結果：実施済】 以下は、過去の実施履歴を表示しています。

| 区分             | 届出日<br>(開始日)  | 届出番号 | 内容 (以下をクリックいただくと措置内容が確認できます)       |
|----------------|---------------|------|------------------------------------|
| サービス<br>キャンペーン | 2020-11-27 開始 | -    | スタートストップSW交換 処置                    |
| サービス<br>キャンペーン | 2019-07-26 開始 | -    | T D U ・ P G M - F I E C Uアップデート 処置 |

(四輪車専用) Honda市場措置専用窓口

《受付時間》 9:00～17:00

※但し、年末年始(12/31～1/3)は除く

フリーダイヤル 0120-280524

閉じる