CASTLE PRESTIGE

Japanese Car Import Specialists

Recall Check

VIN / Chassis RC1-1010081
Make Honda
Source Honda, https://www.honda.co.jp/recall/auto/info/171026_4130.html
Check date 12/10/2026
Result **No outstanding recalls – all completed**

Recall / campaign	What it was	Type	Date filed	Status
Door mirror switch replacement	Door mirror switch contacts may wear, causing the mirrors to fold while driving – mirror switch replaced	Recall	26/10/2017	Completed

The original Japanese result page from the manufacturer follows.

Recall information translated using AI from the manufacturer's records. Every effort has been made to ensure it is accurate.

４輪 リコール・改善対策・サービスキャンペーン 対象車両検索

入力された車台番号　RC1-1010081

お客様が入力された車台番号のおクルマは、リコール等がすべて実施済みです。
安心してお使いいただけます。

【検索結果：実施済】 以下は、過去の実施履歴を表示しています。

区分	届出日 （開始日）	届出番号	内容（以下をクリックいただくと措置内容が確認できます）
リコール	2017-10-26 届出	国4130	ドアミラースイッチ交換　処置

（四輪車専用）Honda市場措置専用窓口

《受付時間》9:00～17:00

※但し、年末年始（12/31～1/3）は除く

フリーダイヤル 0120-280524

閉じる

(C) Honda Motor Co., Ltd. and its subsidiaries and affiliates. All Rights Reserved.