

Recall Check

VIN / Chassis JF2-1202082
Make Honda
Source Honda, https://www.honda.co.jp/recall/auto/info/150903_3630.html
https://www.honda.co.jp/recall/auto/info/141002_3442.html
Check date 12/10/2026
Result **No outstanding recalls – all completed**

Recall / campaign	What it was	Type	Date filed	Status
Plug-top ignition coil replacement	Ignition coil noise-suppression resistor may break, causing misfire, warning light and possible engine stall – ignition coils replaced	Recall	03/09/2015	Completed
ECU reprogramming and starter motor inspection	Engine ECU program error may stop the engine restarting and damage the starter motor – ECU reprogrammed and starter motor inspected (replaced if damaged)	Recall	02/10/2014	Completed

The original Japanese result page from the manufacturer follows.

4輪 リコール・改善対策・サービスキャンペーン 対象車両検索

入力された車台番号 JF2-1202082

お客様が入力された車台番号のおクルマは、リコール等がすべて実施済みです。
安心してお使いいただけます。

【検索結果：実施済】 以下は、過去の実施履歴を表示しています。

区分	届出日 (開始日)	届出番号	内容（以下をクリックいただくと措置内容が確認できます）
リコール	2015-09-03 届出	国3630	プラグトップコイル交換 処置
リコール	2014-10-02 届出	国3442	E C U書換え及びスタータモータ点検 処置

（四輪車専用）Honda市場措置専用窓口

《受付時間》 9:00～17:00

※但し、年末年始（12/31～1/3）は除く

フリーダイヤル 0120-280524

閉じる