CASTLE PRESTIGE

Japanese Car Import Specialists

Recall Check

VIN / Chassis RK5-1364357
Make Honda
Source Honda, https://www.honda.co.jp/recall/auto/info/181115_558.html
Check date 13/10/2026
Result **No outstanding recalls – all completed**

Recall / campaign	What it was	Type	Date filed	Status
Tailgate opening stay defect – remedy	Tailgate gas-strut ball stud mounting may buckle and loosen, so the tailgate could drop suddenly – ball studs checked, re-torqued or replaced	Improvement measure	15/11/2018	Completed

The original Japanese result page from the manufacturer follows.

Recall information translated using AI from the manufacturer's records. Every effort has been made to ensure it is accurate.

４輪 リコール・改善対策・サービスキャンペーン 対象車両検索

入力された車台番号　RK5-1364357

お客様が入力された車台番号のおクルマは、リコール等がすべて実施済みです。
安心してお使いいただけます。

【検索結果：実施済】 以下は、過去の実施履歴を表示しています。

区分	届出日 （開始日）	届出番号	内容（以下をクリックいただくと措置内容が確認できます）
改善対策	2018-11-15 届出	558	テールゲートオープンスイッチ不具合　措置

（四輪車専用）Honda市場措置専用窓口

《受付時間》9:00～17:00

※但し、年末年始（12/31～1/3）は除く

フリーダイヤル 0120-280524

閉じる

(C) Honda Motor Co., Ltd. and its subsidiaries and affiliates. All Rights Reserved.