



Vehicle History Report

VEHICLE DETAILS

Chassis number ¹: ANH20-8099821

Manufacture date: 2010-01

Make: TOYOTA

Model: VELLFIRE

Body: DBA-ANH20W

Grade: Z PLATINUM SELECTION

Engine: 2AZ-FE

Drive: 2WD

Transmission: AT

Title information ²:  **Deregistered to Export** 

Accident / Repair:  **No problem** 

Odometer rollback:  **No problem** 

Manufacturer recall:  **No problem** 

Safety grade ³:  **★★★★★★** 

Contamination risk:  **No problem** 

This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2025-08-13 18:46:40. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD . Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

ODOMETER READINGS HISTORY

Date reported	Data source	Odometer reading (Km)
2023-01-23	MLIT	47400
2025-01-20	MLIT	54100
2025-06-07	TAA Yokohama	54987
2025-06-13	USS Osaka	55000

USE HISTORY

Use in the contaminated regions ⁴	Radioactive contamination test fail ⁵	Commercial use
Not reported	Not reported	Not reported

DETAILED HISTORY

Event date	Location	Odometer reading (Km)	Data source	Details
2010-01			TOYOTA	Manufactured
2010-01			MLIT	First registration
2023-01-23		47400	MLIT	Inspection
2025-01-20	Numazu	54100	MLIT	Inspection

2025-05-30	Numazu		MLIT	Last registration
2025-06-07	Kanagawa	54987	TAA Yokohama	Auctioned
2025-06-13	Osaka	55000	USS Osaka	Auctioned

MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
---------------	-------------	---------------	---------

 Not reported

VEHICLE ASSESSMENT ⁶

Overall Collision Safety Ratings

Driver's seat			Front passenger's seat		
Points	Evaluation	Goal average	Points	Evaluation	Goal average
34.46	★★★★★★	96%	23.51	★★★★★★	98%

* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

Braking performance tests ⁷

Dry road		41.7 m
Wet road		47.1 m

VEHICLE SPECIFICATION

1st gear ratio	2.396 ~ 0.428(MANUAL MODE ATTACHING): CONTINUOUSLY VARIABLE TRANSMISSION	2nd gear ratio	-
3rd gear ratio	-	4th gear ratio	-
5th gear ratio	-	6th gear ratio	-

Additional notes	NFXSK	Airbag position, capacity	-
Body rear overhang	1015	Body type	MV&1BOX
Chassis number embossing position	FRONT FLOOR CROSSMEMBER RIGHT SIDE ON SURFACE	Classification code	0098
Cylinders		Displacement	2360
Electric engine type	-	Electric engine maximum output	-
Electric engine maximum torque	-	Electric engine power	-
Engine maximum power	170ps(125kW)/6000rpm	Engine maximum torque	22.8kg·m(224N·m)/4000rpm
Engine model	2AZ-FE	Frame type	SOLID STRUCTURE
Front shaft weight	1050	Front shock absorber type	
Front stabilizer type	TORSION BAR TYPE	Front tires size	235/50R18 97V
Front tread	1.555	Fuel consumption	11.6
Fuel tank equipment	65	Grade	Z PLATINUM SELECTION
Height	1.900	Length	4.865
Main brakes type	HYDRAULIC TYPE, FRONT: DISK BACK: DISK	Make	TOYOTA
Maximum speed	180	Minimum ground clearance	0.170
Minimum turning radius	5.9	Model	VELLFIRE
Model code	DBA-ANH20W	Mufflers number	
Rear shaft weight	850	Rear shock absorber type	
Rear stabilizer type	-	Rear tires size	235/50R18 97V

Rear tread	1.560	Reverse ratio	1.668
Riding capacity	7	Side brakes type	
Specification code	16086	Stopping distance	50(100)
Transmission type	AT	Weight	1900
Wheel alignment	2WD	Wheelbase	2.950
Width	1.840		

AUCTION DATA

Date: 2025-06-07, Auction: TAA Yokohama, Lot #: 72006

Date:	2025-06-07	Lot #:	72006
Auction name:	TAA Yokohama	Region:	Kanagawa
Make:	TOYOTA	Model:	VELLFIRE
Reg. year:	2010	Mileage (km):	54987
Displacement (cc):	2400	Transmission:	IAT
Color:	PEARL	Model code:	ANH20W
Result:	sold	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

Date: 2025-06-13, Auction: USS Osaka, Lot #: 486

Date:	2025-06-13	Lot #:	486
Auction name:	USS Osaka	Region:	Osaka
Make:	TOYOTA	Model:	VELLFIRE
Reg. year:	2010	Mileage (km):	55000
Displacement (cc):	2400	Transmission:	IA
Color:	PEARL	Model code:	ANH20W
Result:	available	Auction grade:	4
Problem type:	No problem	Problem scale:	None

Contaminated:

No

Airbag:

OK

PHOTOS AND AUCTION SHEETS

出品番号	初度登録	車名	ドア形状	グレード	評価点
72006	H ²² 年	ヴェルファイア	5W	2.4Z プラチナムセレクション	4
	1月	自家用	2400 CC	DBA-ANH20W	外装 C 内装 C
		車歴	排気量	燃料	型式

走行	車検	登録番号	譲渡書類期限	セールスポイント	
54,987 km	年月		月 日	★オークションデビュー★ プッシュスタート 両側パワースライド パワーバックドア	
シフト	エアコン	外装色	乗車定員	最大積載量	
IAT	AAC	パール	7人	kg	
		カラーNo.	輸入車	リサイクル預託金	
		070	知 系	18,290円	

後日発送部品

純正装備

ABS イ7B アルミ PS PW

注意事項欄

車台番号

ANH20-8099821

諸元


長さ 486 幅 184 高さ 190

検査員記入欄

室内汚れ
室内内張傷
シート傷
ハンドルすれ
ミラーA

事務局よりご案内

★厚木ヤード★出品車は神奈川県厚木市
注意：落札後の輸送は全て東日本輸送センター手配



A: 欠 U: A2 B: 欠を伴うA2 P: 要塗装 W: 補修跡 S: 錆 C: 腐食 G: 7D外カ"取点欠" XX: 交換済み X: 要交換 内・外装評価 5段階評価(A・B・C・D・E) 1



¹ Chassis number – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

² Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped

Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

³ Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

⁴ Use in the contaminated regions – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

⁵ Radioactive contamination test – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

⁶ Japan New Car Assessment Program – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

⁷ Braking Performance Tests – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2025 Car VX Limited. All rights reserved.