



Vehicle History Report

VEHICLE DETAILS

Chassis number ¹: ANH20-8194742

Manufacture date: 2011-12

Make: TOYOTA

Model: VELLFIRE

Body: DBA-ANH20W

Grade: 2.4Z

Engine: 2AZ-FE

Drive: 2WD

Transmission: AT

Title information ²:



Deregistered to Export



Accident / Repair:



No problem



Odometer rollback:



No problem



Manufacturer recall:



No problem



Safety grade ³:



★★★★★★



Contamination risk:



No problem



This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2025-07-23 07:54:40. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD . Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

ODOMETER READINGS HISTORY

Date reported	Data source	Odometer reading (Km)
2021-04-08	USS Tokyo	65479
2021-04-28	MLIT	65500
2023-04-25	MLIT	80200
2025-07-08	TAA Kinki	88503

USE HISTORY

Use in the contaminated regions ⁴	Radioactive contamination test fail ⁵	Commercial use
Not reported	Not reported	Not reported

DETAILED HISTORY

Event date	Location	Odometer reading (Km)	Data source	Details
2011-12			TOYOTA	Manufactured
2012-03			MLIT	First registration
2021-04-08	Chiba	65479	USS Tokyo	Auctioned
2021-04-28		65500	MLIT	Inspection

2023-04-25	Wakayama	80200	MLIT	Inspection
2025-03-27	Wakayama		MLIT	Last registration
2025-07-08	Osaka	88503	TAA Kinki	Auctioned

MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
---------------	-------------	---------------	---------

 Not reported

VEHICLE ASSESSMENT ⁶

Overall Collision Safety Ratings

Driver's seat			Front passenger's seat		
Points	Evaluation	Goal average	Points	Evaluation	Goal average
34.46	★★★★★★	96%	23.51	★★★★★★	98%

* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

Braking performance tests ⁷

Dry road		41.7 m
Wet road		47.1 m

VEHICLE SPECIFICATION

1st gear ratio	2.396 ~ 0.428(MANUAL MODE ATTACHING): CONTINUOUSLY VARIABLE TRANSMISSION	2nd gear ratio	-
3rd gear ratio	-	4th gear ratio	-
5th gear ratio	-	6th gear ratio	-

Additional notes	NFXSK	Airbag position, capacity	
Body rear overhang	1015	Body type	MV&1BOX
Chassis number embossing position	FRONT FLOOR CROSSMEMBER RIGHT SIDE ON SURFACE	Classification code	0271
Cylinders	4	Displacement	2360
Electric engine type	-	Electric engine maximum output	-
Electric engine maximum torque	-	Electric engine power	-
Engine maximum power	125/6000(NET)	Engine maximum torque	224/4000(NET)
Engine model	2AZ-FE	Frame type	SOLID STRUCTURE
Front shaft weight	1050	Front shock absorber type	
Front stabilizer type	TORSION BAR TYPE	Front tires size	215/60R17 96H
Front tread	1.580	Fuel consumption	11.6
Fuel tank equipment	65	Grade	2.4Z
Height	1.890	Length	4.885
Main brakes type		Make	TOYOTA
Maximum speed	180	Minimum ground clearance	0.160
Minimum turning radius	5.9	Model	VELLFIRE
Model code	DBA-ANH20W	Mufflers number	
Rear shaft weight	830	Rear shock absorber type	
Rear stabilizer type	-	Rear tires size	215/60R17 96H
Rear tread	1.585	Reverse ratio	1.668
Riding capacity	7	Side brakes type	

Specification code	16086	Stopping distance	50(100)
Transmission type	AT	Weight	1880
Wheel alignment	2WD	Wheelbase	2.950
Width	1.840		

AUCTION DATA

Date: 2021-04-08, Auction: USS Tokyo, Lot #: 35503

Date:	2021-04-08	Lot #:	35503
Auction name:	USS Tokyo	Region:	Chiba
Make:	TOYOTA	Model:	VELLFIRE
Reg. year:	2012	Mileage (km):	65479
Displacement (cc):	2400	Transmission:	AT
Color:	PEARL WHITE	Model code:	ANH20W
Result:	available	Auction grade:	4.5
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK


Date: 2025-07-08, Auction: TAA Kinki, Lot #: 741

Date:	2025-07-08	Lot #:	741
Auction name:	TAA Kinki	Region:	Osaka
Make:	TOYOTA	Model:	VELLFIRE
Reg. year:	2012	Mileage (km):	88503
Displacement (cc):	2400	Transmission:	IAT
Color:	PEARL	Model code:	ANH20W
Result:	sold	Auction grade:	3.5
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

PHOTOS AND AUCTION SHEETS

スライドコーナー

35503	車種 (前年用以外は記入)	排気量	型式	評価点
		2.400	DBA-ANH20W	
	登録年度年月	車名	5ナンバーグレード	2WD
	24/3月	トヨタハイエース	1/5	2.42
				4WD
				内装 B
車種	年	月	ソフト	SR
走行	6.5	87.9	AT	AW
外色	白	カラー	冷房	CS
内色	ベージュ	070	WAC	ナビ
登録	2700	70	キーレスポイント	X28
輸入	ディーラー・並行	左・右	①ナビHDDTV	
			②ナビETC	
			③ナビナビ	
			④ナビナビ	
			⑤ナビナビ	
			⑥ナビナビ	
			⑦ナビナビ	
			⑧ナビナビ	
			⑨ナビナビ	
			⑩ナビナビ	
リサイクル	16360円	7人	登録地	
注意事項	①ナビナビ(CN-H2000) ②ナビナビ			
	③ナビナビ(ナビナビ)			
	④ナビナビ(ナビナビ)			
	⑤ナビナビ(ナビナビ)			
	⑥ナビナビ(ナビナビ)			
	⑦ナビナビ(ナビナビ)			
	⑧ナビナビ(ナビナビ)			
	⑨ナビナビ(ナビナビ)			
	⑩ナビナビ(ナビナビ)			
	⑪ナビナビ(ナビナビ)			
	⑫ナビナビ(ナビナビ)			
	⑬ナビナビ(ナビナビ)			
	⑭ナビナビ(ナビナビ)			
	⑮ナビナビ(ナビナビ)			
	⑯ナビナビ(ナビナビ)			
	⑰ナビナビ(ナビナビ)			
	⑱ナビナビ(ナビナビ)			
	⑲ナビナビ(ナビナビ)			
	⑳ナビナビ(ナビナビ)			
	㉑ナビナビ(ナビナビ)			
	㉒ナビナビ(ナビナビ)			
	㉓ナビナビ(ナビナビ)			
	㉔ナビナビ(ナビナビ)			
	㉕ナビナビ(ナビナビ)			
	㉖ナビナビ(ナビナビ)			
	㉗ナビナビ(ナビナビ)			
	㉘ナビナビ(ナビナビ)			
	㉙ナビナビ(ナビナビ)			
	㉚ナビナビ(ナビナビ)			
	㉛ナビナビ(ナビナビ)			
	㉜ナビナビ(ナビナビ)			
	㉝ナビナビ(ナビナビ)			
	㉞ナビナビ(ナビナビ)			
	㉟ナビナビ(ナビナビ)			
	㊱ナビナビ(ナビナビ)			
	㊲ナビナビ(ナビナビ)			
	㊳ナビナビ(ナビナビ)			
	㊴ナビナビ(ナビナビ)			
	㊵ナビナビ(ナビナビ)			
	㊶ナビナビ(ナビナビ)			
	㊷ナビナビ(ナビナビ)			
	㊸ナビナビ(ナビナビ)			
	㊹ナビナビ(ナビナビ)			
	㊺ナビナビ(ナビナビ)			
	㊻ナビナビ(ナビナビ)			
	㊼ナビナビ(ナビナビ)			
	㊽ナビナビ(ナビナビ)			
	㊾ナビナビ(ナビナビ)			
	㊿ナビナビ(ナビナビ)			



○検査員報告(USS使用欄)

シートベルト
小77

台内寸法 x x (cm)
 長さ 488 cm 幅 174 cm 高さ 189 cm (車体最上の寸法) スペ






出品番号	初度登録	車名	ドア形状	グレード	評価点
741	H²⁴ 年	ヴェルファイア	5W	2.4Z	3.5
	3 月	車歴 自家用	排気量 2400 cc	燃料 ガソリン	型式 DBA-ANH20W
					外装 D
					内装 B

走行		車検	登録番号	譲渡書類期限	セールスポイント	
88,503 km		年 月		月 日	パナソニック9インチナビ 社外20インチアルミ 社外車高調 ドライブレコーダー	
シフト	エアコン	外装色		乗車定員	最大積載量	
IAT	AAC	パール		7 人	kg	
		カラーNo.	内装色	輸入車	リサイクル預託金	
		070	知 系		16,360 円	
後日発送部品					純正装備	
車両取説 キーレス					ABS I7B PS PW	

注意事項欄			車台番号		
			ANH20-8194742		
			諸元		
長さ 488		幅 184		高さ 185	

検査員記入欄
室内内張傷 室内薄汚れ 外装小傷有り
事務局よりご案内



A: 板 U: 413 B: 板を伴う413 P: 異種板 W: 補修板 S: 鋼 C: 腐食 G: 70以上の点板 XX: 交換済み X: 要交換 内・外装評価 5段階評価(A・B・C・D・E) 1



¹ Chassis number – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

² Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped

Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

³ Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

⁴ Use in the contaminated regions – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

⁵ Radioactive contamination test – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

⁶ Japan New Car Assessment Program – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

⁷ Braking Performance Tests – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2025 Car VX Limited. All rights reserved.