



# Vehicle History Report

## VEHICLE DETAILS

**Chassis number <sup>1</sup>:** ANH25-8022889

**Manufacture date:** 2010-06

**Make:** TOYOTA

**Model:** ALPHARD

**Body:** DBA-ANH25W

**Grade:** 240S PRIME SELECTION II

**Engine:** 2AZ-FE

**Drive:** 4WD

**Transmission:** AT

**Title information <sup>2</sup>:**



**Deregistered to Export**



**Accident / Repair:**



**No problem**



**Odometer rollback:**



**No problem**



**Manufacturer recall:**



**No problem**



**Safety grade <sup>3</sup>:**



★★★★★★



**Contamination risk:**









**No problem**



This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2025-09-09 21:19:48. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD . Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.




ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	 Not reported				
Malfunction	 Not reported				
Theft	 Not reported				
Fire damage	 Not reported				
Water damage	 Not reported				
Hail damage	 Not reported				

ODOMETER READINGS HISTORY

Date reported	Data source	Odometer reading (Km)
2021-08-06	MLIT	86000
2023-07-24	MLIT	97100
2025-08-26	TAA Kinki	113183

USE HISTORY

Use in the contaminated regions <sup>4</sup>	Radioactive contamination test fail <sup>5</sup>	Commercial use
 Not reported	 Not reported	 Not reported

DETAILED HISTORY

Event date	Location	Odometer reading (Km)	Data source	Details
2010-06			TOYOTA	Manufactured
2010-08			MLIT	First registration
2021-08-06		86000	MLIT	Inspection
2023-07-24	Kyoto	97100	MLIT	Inspection
2025-08-25	Kyoto		MLIT	Last registration

MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
---------------	-------------	---------------	---------

Not reported


VEHICLE ASSESSMENT <sup>6</sup>

Overall Collision Safety Ratings

Driver's seat			Front passenger's seat		
Points	Evaluation	Goal average	Points	Evaluation	Goal average
32.48	★★★★★★	90%	22.74	★★★★★★	95%

\* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

Braking performance tests <sup>7</sup>



VEHICLE SPECIFICATION

1st gear ratio	2.396 ~ 0.428( MANUAL MODE ATTACHING): CONTINUOUSLY VARIABLE TRANSMISSION	2nd gear ratio	-
3rd gear ratio	-	4th gear ratio	-
5th gear ratio	-	6th gear ratio	-
Additional notes	PFXSK	Airbag position, capacity	-

Body rear overhang	1015	Body type	MV&1BOX
Chassis number embossing position	CYLINDER BLOCK LEFT SIDE	Classification code	0098
Cylinders	4	Displacement	2360
Electric engine type	-	Electric engine maximum output	-
Electric engine maximum torque	-	Electric engine power	-
Engine maximum power	125/6000( NET)	Engine maximum torque	224/4000( NET)
Engine model	2AZ	Frame type	SOLID STRUCTURE
Front shaft weight	1070	Front shock absorber type	
Front stabilizer type	TORSION BAR TYPE	Front tires size	235/50R18 97V
Front tread	1.580	Fuel consumption	11.4
Fuel tank equipment	65	Grade	240S PRIME SELECTION II
Height	1.915	Length	4.865
Main brakes type	HYDRAULIC TYPE, FRONT: DISK BACK: DISK	Make	TOYOTA
Maximum speed	180	Minimum ground clearance	0.180
Minimum turning radius	5.9	Model	ALPHARD
Model code	DBA-ANH25W	Mufflers number	1; 1
Rear shaft weight	900	Rear shock absorber type	
Rear stabilizer type	-	Rear tires size	235/50R18 97V
Rear tread	1.585	Reverse ratio	1.668

Riding capacity	7	Side brakes type	MACHINE CAR WHEEL SHAPE (DRUM TYPE)
Specification code	16087	Stopping distance	50(100)
Transmission type	AT	Weight	1970
Wheel alignment	4WD	Wheelbase	2.950
Width	1.840		

AUCTION DATA

Date: 2025-08-26, Auction: TAA Kinki, Lot #: 70065

Date:	2025-08-26	Lot #:	70065
Auction name:	<a href="#">TAA Kinki</a>	Region:	Osaka
Make:	TOYOTA	Model:	ALPHARD
Reg. year:	2010	Mileage (km):	113183
Displacement (cc):	2400	Transmission:	IAT
Color:	PEARL	Model code:	ANH25W
Result:	sold	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

PHOTOS AND AUCTION SHEETS

出 品 番 号	初度登録	車 名	ドア形状	グ レード	評価点
70065	H <sup>22</sup> 年	アルファード	5W	240S プライムセレクション2 4WD	4
	8 月	自家用	排 気 量 2400 cc	燃 料 ガソリン	型 式 DBA-ANH25W
					外装 内装 B C

走 行	車 検	登 録 番 号	譲渡書類期限	セールスポイント
113,183 km	年 月		月 日	★オークションデビュー★
シフト エアコン	外 装 色	乗車定員	最大積載量	
IAT AAC	パール	7 人	kg	
	カ ラー No.	内 装 色	輸 入 車	リサイクル預託金
	070	知 系		18,290 円
後日発送部品				純 正 装 備
				ABS イ7B PS PW

注 意 事 項 欄	車 台 番 号
	ANH25-8022889
	諸 元
	長さ 幅 高さ

検 査 員 記 入 欄	
下廻り S、AU 外装うすい線キズ 室内汚れ ハンドルすれ ダッシュ板傷 バンパー下A	
事 務 局 より ご 案 内 ★京都特設ヤード出品★出品車は京都府八幡市 注意：搬出は京都特設ヤードになります	

A:穴 U:へこ B:穴を伴うへこ P:要塗装 W:補修跡 S:錆 C:腐食 G:70点か8点か XX:交換済み X:要交換 内・外装評価 5段階評価(A・B・C・D・E) 1









**<sup>1</sup> Chassis number** – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

**<sup>2</sup> Title information:**

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped

Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

**<sup>3</sup> Determining the overall collision safety performance evaluation** – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

**<sup>4</sup> Use in the contaminated regions** – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

**<sup>5</sup> Radioactive contamination test** – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

**<sup>6</sup> Japan New Car Assessment Program** – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

**<sup>7</sup> Braking Performance Tests** – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2025 Car VX Limited. All rights reserved.