

PORSCHE

Dealership Service History

VIN: WP1ZZZ95ZGLB90325

2016 Macan Turbo (95B-AF1)

Total Warranty Repair Days: 87

Total Number of Jobs: 14



Warranty Details

Description	From	To	Coverage	Mileage Limit	KM Limit
New vehicle	August 3, 2015	August 2, 2018		N/A	N/A
New vehicle	August 3, 2015	August 3, 2022	Extended warranty for transfer box	N/A	N/A
Corrosion	August 3, 2018	August 3, 2027		N/A	N/A
Pre-owned	August 5, 2018	August 4, 2019		N/A	N/A

Service Job #1 - Porsche Center Hamadayama

Service Dates: June 12, 2016 - June 12, 2016

Odometer Value: 7,766 Kilometers

Breakdown Status: No

Services Performed

Location	Symptom	Information	Warranty Use
Replacing fuel low-pressure line in the engine compartment	Recall campaign		✓
Entire vehicle – General	Technical inspection §	3000km点検	
Re-program all-wheel drive control unit	Workshop campaign		✓

Service Job #2 - Porsche Center Meguro

Service Dates: August 2, 2016 - August 3, 2016
Odometer Value: 8,780 Kilometers
Breakdown Status: No

Services Performed

Location	Symptom	Information	Warranty Use
Entire vehicle – General	Minor maintenance	1 2ヶ月点検実施	

Service Job #3 - Porsche Center Meguro

Service Dates: July 21, 2017 - July 21, 2017
Odometer Value: 19,115 Kilometers
Breakdown Status: No

Services Performed

Location	Symptom	Information	Warranty Use
Repairs to flange of fuel filter unit	Recall campaign		✓
Retrofit low-pass filter for tweeter	Workshop campaign		✓

Service Job #4 - Porsche Center Hamadayama

Service Dates: March 13, 2018 - March 13, 2018
Odometer Value: 26,109 Kilometers
Breakdown Status: No

Services Performed

Location	Symptom	Information	Warranty Use
Entire vehicle – General	General workshop visit / Service (DMS)		

Service Job #5 - Porsche Center Hamadayama

Service Dates: August 2, 2018 - August 2, 2018
Odometer Value: 29,485 Kilometers
Breakdown Status: No

Services Performed

Location	Symptom	Information	Warranty Use
Entire vehicle – General	Technical inspection §	車検整備	

Service Job #6 - Porsche Center Hamadayama

Service Dates: August 4, 2018 - August 5, 2018
Odometer Value: 29,566 Kilometers
Breakdown Status: No

Services Performed

Location	Symptom	Information	Warranty Use
Entire vehicle – General	Warranty check for pre-owned Porsche vehicles	保証延長 1 年間 111項目チェックシート による点検 8/2に 車検完了、追加で 保証延長	

Service Job #7 - Porsche Center Meguro

Service Dates: January 22, 2019 - January 22, 2019
Odometer Value: 33,185 Kilometers
Breakdown Status: No

Services Performed

Location	Symptom	Information	Warranty Use
Entire vehicle – General	Technical inspection §	エンジンオイル補 充 1 , 2 L	

Service Job #8 - Porsche Center Meguro

Service Dates: September 13, 2019 - September 13, 2019
Odometer Value: 38,022 Kilometers
Breakdown Status: No

Services Performed

Location	Symptom	Information	Warranty Use
Entire vehicle – General	Technical inspection §	エンジンオイル& フィルター交換	

Service Job #9 - Porsche Center Meguro

Service Dates: September 1, 2020 - September 7, 2020
Odometer Value: 44,794 Kilometers
Breakdown Status: No

Services Performed

Location	Symptom	Information	Warranty Use
Reworking or replacing service cover for fuel pump	Recall campaign		✓
Entire vehicle – General	Major maintenance	車検	

Service Job #10 - Porsche Center Meguro

Service Dates: June 4, 2021 - June 14, 2021
Odometer Value: 52,094 Kilometers
Breakdown Status: No

Services Performed

Location	Symptom	Information	Warranty Use
Transfer box	Vibrates, shakes		✓

Service Job #11 - Porsche Center Meguro

Service Dates: August 18, 2022 - August 23, 2022
Odometer Value: 60,608 Kilometers
Breakdown Status: No

Services Performed

Location	Symptom	Information	Warranty Use
Entire vehicle – General	Technical inspection §		

Service Job #12 - Porsche Center Meguro

Service Dates: January 25, 2023 - March 20, 2023
Odometer Value: 63,309 Kilometers
Breakdown Status: No

Services Performed

Location	Symptom	Information	Warranty Use
Entire vehicle – General	Technical inspection §	異音点検	

Service Job #13 - Porsche Center Meguro

Service Dates: November 14, 2023 - November 14, 2023
Odometer Value: 68,261 Kilometers
Breakdown Status: No

Services Performed

Location	Symptom	Information	Warranty Use
Re-programming instrument cluster	Recall campaign		✓

Service Job #14 - Porsche Center Takasaki-Maebashi

Service Dates: August 29, 2024 - September 4, 2024
Odometer Value: 71,598 Kilometers
Breakdown Status: No

Services Performed

Location	Symptom	Information	Warranty Use
Entire vehicle – General	General workshop visit / Service (DMS)		

While we strive for accuracy, VIN Analytics is not responsible for any errors or omissions on this page. Please verify any details with your local Porsche Dealership or Porsche Cars Customer Service. We assume no responsibility for errors in this report and disclaim all warranties, including implied warranties of merchantability or fitness for a particular purpose. All trademarks and registered trademarks are the property of their respective owners. All trademarks, trade names, service marks, product names, option names and logos are the property of their respective owners.

© 2025 VIN Analytics, LLC. All rights reserved.

