



Vehicle History Report

VEHICLE DETAILS

Chassis number ¹: RC1-1027215

Manufacture date: 2014-03-18

Make: HONDA

Model: ODYSSEY

Body: DBA-RC1

Grade: ABSOLUTE EX

Engine: K24W

Drive: 2WD

Transmission: AT

Title information ²:  **Registered** 

Accident / Repair:  **No problem** 

Odometer rollback:  **No problem** 

Manufacturer recall:  **No problem** 

Safety grade ³:  **★★★★★** 

Contamination risk:  **No problem** 

This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2025-11-26 23:56:38. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD . Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

ODOMETER READINGS HISTORY

Date reported	Data source	Odometer reading (Km)
2023-05-29	MLIT	84800
2025-06-09	MLIT	95300
2025-11-03	Honda Tokyo	96000
2025-11-19	CAA Kyouyuu	96023

USE HISTORY

Use in the contaminated regions ⁴	Radioactive contamination test fail ⁵	Commercial use
Not reported	Not reported	Not reported

DETAILED HISTORY

Event date	Location	Odometer reading (Km)	Data source	Details
2014-03-18			HONDA	Manufactured
2014-06			MLIT	First registration
2023-05-29		84800	MLIT	Inspection
2025-06-09	Matsumoto	95300	MLIT	Inspection

2025-10-28	Matsumoto		MLIT	Last registration
2025-11-03	Tokyo	96000	Honda Tokyo	Auctioned
2025-11-19		96023	CAA Kyouyuu	Auctioned

MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
---------------	-------------	---------------	---------

 Not reported

VEHICLE ASSESSMENT ⁶

Overall Collision Safety Ratings

Driver's seat			Front passenger's seat		
Points	Evaluation	Goal average	Points	Evaluation	Goal average
32.88	★★★★★★	91%	23.22	★★★★★★	97%

* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

Braking performance tests ⁷

Dry road		40.1 m
Wet road		43.1 m

VEHICLE SPECIFICATION

1st gear ratio	2.645 ~ 0.405	2nd gear ratio
3rd gear ratio		4th gear ratio
5th gear ratio		6th gear ratio
Additional notes		Airbag position, capacity

Body rear overhang		Body type	MV&1BOX
Chassis number embossing position		Classification code	48
Cylinders	4	Displacement	2350
Electric engine type		Electric engine maximum output	
Electric engine maximum torque		Electric engine power	
Engine maximum power	190PS(140KW)/6400RPM	Engine maximum torque	24.2kg· m(237N· m)/4000rpm
Engine model	K24W	Frame type	
Front shaft weight	1000	Front shock absorber type	
Front stabilizer type		Front tires size	225/45R18 91W
Front tread	1560	Fuel consumption	
Fuel tank equipment	55	Grade	ABSOLUTE EX
Height	168	Length	483
Main brakes type		Make	HONDA
Maximum speed		Minimum ground clearance	
Minimum turning radius	5400	Model	ODYSSEY
Model code	DBA-RC1	Mufflers number	
Rear shaft weight	830	Rear shock absorber type	
Rear stabilizer type		Rear tires size	225/45R18 91W
Rear tread	1560	Reverse ratio	1.858 ~ 1.264
Riding capacity	7	Side brakes type	
Specification code	17637	Stopping distance	
Transmission type	AT	Weight	1830
Wheel alignment	2WD	Wheelbase	2900
Width	182		


Date: 2025-11-03, Auction: Honda Tokyo, Lot #: 20062

Date:	2025-11-03	Lot #:	20062
Auction name:	Honda Tokyo	Region:	Tokyo
Make:	HONDA	Model:	ODYSSEY
Reg. year:	2014	Mileage (km):	96000
Displacement (cc):	2400	Transmission:	DAT
Color:	DARK BLUE	Model code:	RC1
Result:	sold	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

Date: 2025-11-19, Auction: CAA Kyouyuu, Lot #: 22436



Date:	2025-11-19	Lot #:	22436
Auction name:	CAA Kyouyuu	Region:	
Make:	HONDA	Model:	ODYSSEY
Reg. year:	2014	Mileage (km):	96023
Displacement (cc):	2400	Transmission:	AT
Color:	BLACK	Model code:	RC1
Result:	available	Auction grade:	4.5
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

PHOTOS AND AUCTION SHEETS
















初年度登録 26年6月	車名 オデッセイ		ドア・形状 5・W	グレード アブソルート・EX		駆動	総合評価点 4.5
型式 DBA RC1	排気量 2,400_{CC}	燃料 ガソリン	車歴 自家用	定員(最大) 7名	積載量(最大) Kg	輸入車 年行'A	
ミッション AT	エアコン WAC	カラーNo. NH820PX	外装色 ブラック	装備 PS 7 _ピ PW TV I7B 革 ABS アルミ		保証書 取説	内装評価 B
走行距離 96,023_{km}	車検 9年6月	登録ナンバー 名変中	ほか装備		車台番号 RC1-1027215	預託金 14,420円	

セールスポイント	特記事項・不具合箇所
<ul style="list-style-type: none"> ★コンフォートビューパッケージ ★あんしんパッケージ ★純正ナビ★フルセグ★リヤカメラ ★両側パワースライドドア★ETC ★ハーフレザー★LEDライト ★プッシュスタート★スマートキー 	内装汚れ 内張り傷 シートすれ ハンドルすれ カーペットすれ
注意事項	



ver. 00000001





¹ Chassis number – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

² Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped

Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

³ Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

⁴ Use in the contaminated regions – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

⁵ Radioactive contamination test – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

⁶ Japan New Car Assessment Program – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

⁷ Braking Performance Tests – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2025 Car VX Limited. All rights reserved.