



Vehicle History Report

VEHICLE DETAILS

Chassis number ¹: ZWR80-0088366

Manufacture date: 2015-01

Make: TOYOTA

Model: NOAH

Body: DAA-ZWR80G

Grade: HYBRID G

Engine: 2ZR-FXE

Drive: 2WD

Transmission: AT

Title information ²:



Deregistered to Export



Accident / Repair:



No problem



Odometer rollback:



No problem



Manufacturer recall:



No problem



Safety grade ³:



★★★★★



Contamination risk:



No problem



This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2026-02-17 09:12:43. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD . Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

ODOMETER READINGS HISTORY

Date reported	Data source	Odometer reading (Km)
2022-02-03	MLIT	60800
2024-02-07	MLIT	79200
2026-01-30	USS Osaka	95205


USE HISTORY

Use in the contaminated regions ⁴	Radioactive contamination test fail ⁵	Commercial use
Not reported	Not reported	Not reported

DETAILED HISTORY

Event date	Location	Odometer reading (Km)	Data source	Details
2015-01			TOYOTA	Manufactured
2015-02			MLIT	First registration
2022-02-03		60800	MLIT	Inspection
2024-02-07	Kobe	79200	MLIT	Inspection
2026-01-29	Kobe		MLIT	Last registration

MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
 Not reported			

VEHICLE ASSESSMENT ⁶

Overall Collision Safety Ratings

Driver's seat			Front passenger's seat		
Points	Evaluation	Goal average	Points	Evaluation	Goal average
11.18	★★★★★	93%	9.8	★★★★	82%

* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

Braking performance tests ⁷

Dry road



41.8 m

Wet road



44.6 m

VEHICLE SPECIFICATION

1st gear ratio

2nd gear ratio

3rd gear ratio

4th gear ratio

5th gear ratio

6th gear ratio

Additional notes

Airbag position,
capacity

Body rear overhang

Body type

MV&1BOX

Chassis number embossing position		Classification code	5
Cylinders	4	Displacement	1790
Electric engine type		Electric engine maximum output	
Electric engine maximum torque		Electric engine power	
Engine maximum power	99ps(73kW)/5200rpm	Engine maximum torque	14.5kg· m(142N· m)/4000rpm
Engine model	2ZR-FXE	Frame type	
Front shaft weight	910	Front shock absorber type	
Front stabilizer type		Front tires size	195/65R15
Front tread	1480	Fuel consumption	
Fuel tank equipment	55	Grade	HYBRID G
Height	182	Length	469
Main brakes type		Make	TOYOTA
Maximum speed		Minimum ground clearance	
Minimum turning radius	5.5	Model	NOAH
Model code	DAA-ZWR80G	Mufflers number	
Rear shaft weight	710	Rear shock absorber type	
Rear stabilizer type		Rear tires size	195/65R15
Rear tread	1480	Reverse ratio	
Riding capacity	7	Side brakes type	
Specification code	17698	Stopping distance	
Transmission type	AT	Weight	1620
Wheel alignment	2WD	Wheelbase	2850
Width	169		

Date: 2026-01-30, Auction: USS Osaka, Lot #: 20232

Date:	2026-01-30	Lot #:	20232
Auction name:	USS Osaka	Region:	Osaka
Make:	TOYOTA	Model:	NOAH
Reg. year:	2015	Mileage (km):	95205
Displacement (cc):	1800	Transmission:	AT
Color:	BROWN	Model code:	ZWR80G
Result:	available	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

PHOTOS AND AUCTION SHEETS


プライムタイムコーナー

20232	車種 (国産車以外は記入)	排気量	型式	4
		1.800cc	DAA-ZWR80G	
	初年度登録年月	車名	グレード	2WD
	H27/2月	1ア	MT/1.8 G	4WD
				内装 C

車検	年	月	シフト	AT	SR	AW	ES	EW
走行	95,205	km	冷房	W.A/C	カワ	TV	ナビ	C2B
外色	元色: 白 新色: 白	カラー	有・無	セールスポイント 社外ナビ (ナビ=ア) ETC				
燃料	ガソリン・軽油・L	内装色	クロ	名義変更済				
輸入国	輸入区分	ハンドル	左・右	月	日			

リサイクル 標記	12,470円	乗車定員	7人	登録地	
○注意事項 (除却・不具合箇所および故障等)	バックカメラ映りません				
	感				

○検査員報告 (USS使用時)	
ル-ム内汚れ	
ホイルキス	
ドアスリキス	
外装上面Pア	



【乗台内寸】	長さ	幅	高さ	※(車検用上寸法)
	469 cm	169 cm	182 cm	

※必ず予備検査員ールペンで記入してください。水色ボールペンは使用できません。

1. SR・AW・ES・EWは必ず記入してください。

¹ Chassis number – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

² Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped

Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

³ Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

⁴ Use in the contaminated regions – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

⁵ Radioactive contamination test – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

⁶ Japan New Car Assessment Program – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

⁷ Braking Performance Tests – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2026 Car VX Limited. All rights reserved.