



# Vehicle History Report

## VEHICLE DETAILS

**Chassis number <sup>1</sup>:** GP3-1062417

**Manufacture date:** 2012-07-31

**Make:** HONDA

**Model:** FREED

**Body:** DAA-GP3

**Grade:** HYBRID JUST SELECTION

**Engine:** LEA-MF6

**Drive:** 2WD

**Transmission:** AT

**Title information <sup>2</sup>:**



**Deregistered to Export**



**Accident / Repair:**



**No problem**



**Odometer rollback:**



**No problem**



**Manufacturer recall:**



**No problem**



**Safety grade <sup>3</sup>:**



★★★★★



**Contamination risk:**



**No problem**



This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2026-04-11 08:33:03. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD . Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

## ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

## ODOMETER READINGS HISTORY

Date reported	Data source	Odometer reading (Km)
2022-02-28	MLIT	91300
2024-03-01	MLIT	106400
2026-03-25	CAA Chubu	119831


## USE HISTORY

<b>Use in the contaminated regions <sup>4</sup></b>	<b>Radioactive contamination test fail <sup>5</sup></b>	<b>Commercial use</b>
Not reported	Not reported	Not reported

## DETAILED HISTORY

Event date	Location	Odometer reading (Km)	Data source	Details
2012-07-31			HONDA	Manufactured
2013-03			MLIT	First registration
2022-02-28		91300	MLIT	Inspection
2024-03-01	Fukui	106400	MLIT	Inspection
2026-03-19	Fukui		MLIT	Last registration

## MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
 Not reported			

## VEHICLE ASSESSMENT <sup>6</sup>

### Overall Collision Safety Ratings

Driver's seat			Front passenger's seat		
Points	Evaluation	Goal average	Points	Evaluation	Goal average
32.64	★★★★★	91%	22.31	★★★★★	93%

\* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

### Braking performance tests <sup>7</sup>

Dry road  44.5 m

Wet road  48.1 m

## VEHICLE SPECIFICATION

<b>1st gear ratio</b>	2.526 ~ 0.421: CONTINUOUSLY VARIABLE TRANSMISSION	<b>2nd gear ratio</b>	-
-----------------------	---	-----------------------	---

<b>3rd gear ratio</b>	-	<b>4th gear ratio</b>	-
-----------------------	---	-----------------------	---

<b>5th gear ratio</b>	-	<b>6th gear ratio</b>	-
-----------------------	---	-----------------------	---

**Additional notes**

**Airbag position,  
capacity**

<b>Body rear overhang</b>	665	<b>Body type</b>	MV&1BOX
<b>Chassis number embossing position</b>		<b>Classification code</b>	0008
<b>Cylinders</b>	4	<b>Displacement</b>	1490
<b>Electric engine type</b>		<b>Electric engine maximum output</b>	10/1500
<b>Electric engine maximum torque</b>	92/500	<b>Electric engine power</b>	9
<b>Engine maximum power</b>	65/5400( NET)	<b>Engine maximum torque</b>	132/4200( NET)
<b>Engine model</b>	LEA-MF6	<b>Frame type</b>	SOLID STRUCTURE
<b>Front shaft weight</b>	790	<b>Front shock absorber type</b>	
<b>Front stabilizer type</b>	TORSION· BAR TYPE	<b>Front tires size</b>	185/65R15 88S DESIGNATION EQUIPMENT ETC.
<b>Front tread</b>	1.480	<b>Fuel consumption</b>	24.0
<b>Fuel tank equipment</b>	42	<b>Grade</b>	HYBRID JUST SELECTION
<b>Height</b>	1.715	<b>Length</b>	4.215
<b>Main brakes type</b>		<b>Make</b>	HONDA
<b>Maximum speed</b>	165	<b>Minimum ground clearance</b>	0.150
<b>Minimum turning radius</b>	5.2	<b>Model</b>	FREED
<b>Model code</b>	DAA-GP3	<b>Mufflers number</b>	
<b>Rear shaft weight</b>	610	<b>Rear shock absorber type</b>	
<b>Rear stabilizer type</b>	TORSION· BAR TYPE	<b>Rear tires size</b>	185/65R15 88S DESIGNATION EQUIPMENT ETC.
<b>Rear tread</b>	1.475	<b>Reverse ratio</b>	4.510 ~ 1.641: CONTINUOUSLY VARIABLE TRANSMISSION

Riding capacity 7

Side brakes type

Specification code 17007

Stopping distance 53(100)

Transmission type AT

Weight 1400

Wheel alignment 2WD

Wheelbase 2.740

Width 1.695

## AUCTION DATA

Date: 2026-03-25, Auction: CAA Chubu, Lot #: 90509

Date: 2026-03-25 Lot #: 90509

Auction name: [CAA Chubu](#) Region: Aichi

Make: HONDA Model: FREED HYBRID

Reg. year: 2013 Mileage (km): 119831

Displacement (cc): 1500 Transmission: IAT

Color: PEARL WHITE Model code: GP3

Result: sold Auction grade: 4

Problem type: No problem Problem scale: None

Contaminated: No Airbag: OK


## PHOTOS AND AUCTION SHEETS

出品番号	初度登録	車名	ドア形状	グレード	評価点
90509 初出品	H25	フリードハイブリッド		ジャストセレクション	4
	年	車歴	排気量	燃料	型式
	3月	自家用	1500cc	ガソリン	DAA-GP3
					外装 内装
					B B

走行	車検	登録番号	譲渡書類期限	セールスポイント	
119,831 km	年 月		月 日	★ユーザー買取車 ★純正ナビTV、ETC ★クルコン・パワースラ ★オートHID ★スマートキー	
シフト	エアコン	外装色	乗車定員	最大積載量	
IAT	AAC	パールホワイト	7人	kg	
		カラーNo.	輸入車	リサイクル預託金	
		NH624P	系	12,090円	
後日発送部品				純正装備	
保証書 車両取説				北 TV 17B PS PW	

注意事項欄			車台番号		
			GP3-1062417		
			諸元		
長さ		幅	高さ		

検査員記入欄
ロアサポート小歪み ハンドルすれ 室内薄汚れ リヤ下廻りAU 下廻りS 外装小傷有り 外ホイール
事務局よりご案内
売切リスタート




A:キズ U:欠陥 B:キズを伴う欠陥 P:要塗装 W:補修箇所 S:錆 C:腐食、穴 G:ボディ材の2点キズ XX:交換済み X:要交換 欠:欠品 内・外装評価 5段階5段階順(A・B・C・D・E) 1















**<sup>1</sup> Chassis number** – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

**<sup>2</sup> Title information:**

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped

Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

**<sup>3</sup> Determining the overall collision safety performance evaluation** – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

**<sup>4</sup> Use in the contaminated regions** – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

**<sup>5</sup> Radioactive contamination test** – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

**<sup>6</sup> Japan New Car Assessment Program** – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

**<sup>7</sup> Braking Performance Tests** – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2026 Car VX Limited. All rights reserved.