



Vehicle History Report

VEHICLE DETAILS

Chassis number ¹: Z12-203883

Manufacture date: 2012-04

Make: NISSAN

Model: CUBE

Body: DBA-Z12

Grade: 15X INDIGO + PLASMA

Engine: HR15

Drive: 2WD

Transmission: AT

Title information ²:



Deregistered
Temporarily



Accident / Repair:



No problem



**Odometer
rollback:**



No problem



**Manufacturer
recall:**



No problem



Safety grade ³:



★★★★★



**Contamination
risk:**



No problem



This vehicle does not qualify for Buyback Guarantee

Average Market Price



Unfortunately, this vehicle does not qualify for our Buyback Guarantee program.

[About Buyback Guarantee](#)



¥270,000

This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2023-02-08 06:18:50. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD . Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

ODOMETER READINGS HISTORY

Date reported	Data source	Odometer reading (Km)
2019-05-15	MLIT	97800
2021-05-24	MLIT	107600
2023-02-01	CAA Chubu	115744


USE HISTORY

Use in the contaminated regions ⁴	Radioactive contamination test fail ⁵	Commercial use
Not reported	Not reported	Not reported

DETAILED HISTORY

Event date	Location	Odometer reading (Km)	Data source	Details
2012-04			NISSAN	Manufactured
2012-05			MLIT	First registration
2019-05-15		97800	MLIT	Inspection
2021-05-24	Komaki	107600	MLIT	Inspection
2023-01-18	Komaki		MLIT	Last registration

MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
 Not reported			

VEHICLE ASSESSMENT ⁶

Overall Collision Safety Ratings

Driver's seat			Front passenger's seat		
Points	Evaluation	Goal average	Points	Evaluation	Goal average
33.36	★★★★★★	93%	22.46	★★★★★★	94%

* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

Braking performance tests ⁷

Dry road



Wet road



VEHICLE SPECIFICATION

1st gear ratio	2.561 ~ 0.427	2nd gear ratio	-
3rd gear ratio	-	4th gear ratio	-
5th gear ratio	-	6th gear ratio	-
Additional notes	-	Airbag position, capacity	-
Body rear overhang	560	Body type	STATION WAGON

Chassis number embossing position	COWL TOP PANEL RIGHT SIDE	Classification code	0029
Cylinders	4	Displacement	1490
Electric engine type	-	Electric engine maximum output	-
Electric engine maximum torque	-	Electric engine power	-
Engine maximum power	80/6000(NET)	Engine maximum torque	148/4400(NET)
Engine model	HR15	Frame type	SOLID STRUCTURE
Front shaft weight	720	Front shock absorber type	
Front stabilizer type	TORSION BAR TYPE	Front tires size	175/65R15 84S
Front tread	1.480	Fuel consumption	20.0
Fuel tank equipment	45	Grade	15X INDIGO + PLASMA
Height	1.650	Length	3.890
Main brakes type	HYDRAULIC TYPE, FRONT: DISK BACK: LEADING TRAILING	Make	NISSAN
Maximum speed	170(推定)	Minimum ground clearance	0.160
Minimum turning radius	4.6	Model	CUBE
Model code	DBA-Z12	Mufflers number	
Rear shaft weight	460	Rear shock absorber type	
Rear stabilizer type	TORSION BAR TYPE	Rear tires size	175/65R15 84S
Rear tread	1.485	Reverse ratio	2.619
Riding capacity	5	Side brakes type	MACHINE CAR WHEEL 制動 SHAPE(DRUM TYPE)
Specification code	16207	Stopping distance	62(100)
Transmission type	AT	Weight	1180

Wheel alignment 2WD

Wheelbase 2.530

Width 1.695

AUCTION DATA

Date: 2023-02-01, Auction: CAA Chubu, Lot #: 30358

Date: 2023-02-01 Lot #: 30358

Auction name: [CAA Chubu](#) Region: Aichi

Make: NISSAN Model: CUBE

Reg. year: 2012 Mileage (km): 115744

Displacement (cc): 1500 Transmission: AT

Color: BROWN Model code: Z12

Result: sold Auction grade: 4

Problem type: No problem Problem scale: None

Contaminated: No Airbag: OK


PHOTOS AND AUCTION SHEETS

出品番号	初度登録	車名	ドア形状	グレード	評価点
30358 初出品	H24年	キューブ		15X インデコ+プラスマ	4
	5月	車歴 自家用	排気量 1500cc	燃料 ガソリン	型式 DBA-Z12
					外装 内装 C B

走行	車検	登録番号	名変期限	セールスポイント	
115,744 km	年月		月日	★ユーザー買取車	
シフト	エアコン	外装色	乗車定員	最大積載量	
AT	AAC	ブラウン	5人	kg	
		カラーNo.	輸入車	リサイクル預託金	
		L50	系	9,460円	
後日発送部品				純正装備	
				北 17B PS PW	

注意事項欄			車台番号		
			Z12-203883		
			諸元		
長さ		幅	高さ		

検査員記入欄
室内薄汚れ シートすれ小 サイドミラーP剥がれ ホイールカバーA 外装小傷有り 下廻りS小
事務局よりご案内
キーケース



A:キズ U:欠陥 B:キズを伴う欠陥 P:要塗装 W:補修箇 S:錆 C:腐食、穴 G:ボディ材の2点キズ XX:交換済み X:要交換 欠:欠品 内・外装評価 5段階5段階順(A・B・C・D・E) 1













¹ Chassis number – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

² Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped

Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

³ Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

⁴ Use in the contaminated regions – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

⁵ Radioactive contamination test – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

⁶ Japan New Car Assessment Program – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

⁷ Braking Performance Tests – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2023 Car VX Limited. All rights reserved.