

VEHICLE DETAILS

Chassis number ¹: ANH20-8098420

Manufacture date: 2010-01

Make: TOYOTA

Model: VELLFIRE

Body: DBA-ANH20W

Grade: 2.4Z

Engine: 2AZ

Drive: 2WD

Transmission: AT

Title information ²:



Deregistered
Temporarily



Accident / Repair:



No problem



**Odometer
rollback:**



No problem



**Manufacturer
recall:**



No problem



Safety grade ³:



★★★★★



**Contamination
risk:**



No problem



This vehicle does not qualify for Buyback Guarantee



Unfortunately, this vehicle does not qualify for our Buyback Guarantee program.

[About Buyback Guarantee](#)

Average Market Price



¥800,000

This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2023-02-20 07:37:08. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD . Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

ODOMETER READINGS HISTORY

Date reported	Data source	Odometer reading (Km)
2019-01-22	MLIT	63300
2021-02-01	MLIT	72900
2023-02-15	Guliver Oneprice	78000
2023-02-18	USS HAA Kobe	78622

USE HISTORY

Use in the contaminated regions ⁴	Radioactive contamination test fail ⁵	Commercial use
Not reported	Not reported	Not reported

DETAILED HISTORY

Event date	Location	Odometer reading (Km)	Data source	Details
2010-01			TOYOTA	Manufactured
2010-01			MLIT	First registration
2019-01-22		63300	MLIT	Inspection
2021-02-01	Kobe	72900	MLIT	Inspection

2023-02-06	Kobe		MLIT	Last registration
2023-02-15		78000	Guliver Oneprice	Auctioned
2023-02-18	Hyogo	78622	USS HAA Kobe	Auctioned

MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
---------------	-------------	---------------	---------

 Not reported



VEHICLE ASSESSMENT ⁶

Overall Collision Safety Ratings

Driver's seat			Front passenger's seat		
Points	Evaluation	Goal average	Points	Evaluation	Goal average
34.46	★★★★★★	96%	23.51	★★★★★★	98%

* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

Braking performance tests ⁷

Dry road		41.7 m
Wet road		47.1 m

VEHICLE SPECIFICATION

1st gear ratio	2.396 ~ 0.428(MANUAL MODE ATTACHING): CONTINUOUSLY VARIABLE TRANSMISSION	2nd gear ratio	-
3rd gear ratio	-	4th gear ratio	-
5th gear ratio	-	6th gear ratio	-

Additional notes	NRXSK	Airbag position, capacity	-
Body rear overhang	1015	Body type	STATION WAGON
Chassis number embossing position	FRONT FLOOR CROSSMEMBER RIGHT SIDE ON SURFACE	Classification code	0038
Cylinders	4	Displacement	2360
Electric engine type	-	Electric engine maximum output	-
Electric engine maximum torque	-	Electric engine power	-
Engine maximum power	125/6000(NET)	Engine maximum torque	224/4000(NET)
Engine model	2AZ	Frame type	SOLID STRUCTURE
Front shaft weight	1050	Front shock absorber type	
Front stabilizer type	TORSION BAR TYPE	Front tires size	215/60R17 96H 235/50R18 97V
Front tread	1555	Fuel consumption	11.6
Fuel tank equipment	65	Grade	2.4Z
Height	1900	Length	4865
Main brakes type	HYDRAULIC TYPE, DISK HYDRAULIC TYPE, DISK	Make	TOYOTA
Maximum speed	180	Minimum ground clearance	170
Minimum turning radius	5.9	Model	VELLFIRE
Model code	DBA-ANH20W	Mufflers number	
Rear shaft weight	830	Rear shock absorber type	

Rear stabilizer type	-	Rear tires size	215/60R17 96H 235/50R18 97V
Rear tread	1560	Reverse ratio	1.668
Riding capacity	8	Side brakes type	MACHINE CAR WHEEL 制動 SHAPE(DRUM TYPE)
Specification code	16086	Stopping distance	50(100)
Transmission type	AT	Weight	1880
Wheel alignment	2WD	Wheelbase	2950
Width	1840		

AUCTION DATA

Date: 2023-02-15, Auction: Guliver Oneprice, Lot #: 13712


Date:	2023-02-15	Lot #:	13712
Auction name:	Guliver Oneprice	Region:	
Make:	TOYOTA	Model:	VELLFIRE
Reg. year:	2010	Mileage (km):	78000
Displacement (cc):	2400	Transmission:	FAT
Color:	BLACK	Model code:	ANH20W
Result:	available	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

Date: 2023-02-18, Auction: USS HAA Kobe, Lot #: 37084

Date:	2023-02-18	Lot #:	37084
Auction name:	USS HAA Kobe	Region:	Hyogo
Make:	TOYOTA	Model:	VELLFIRE
Reg. year:	2010	Mileage (km):	78622
Displacement (cc):	2400	Transmission:	IA

Color:	BLACK	Model code:	ANH20W
Result:	available	Auction grade:	4.5
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

PHOTOS AND AUCTION SHEETS






プライムタイムコーナー

37084	車種 (旧車種以外は記入) 排気量	型式	評価点
	2400 CC	PBA-ANH 20 W	45
	初年度登録年月 車名	グレード	2WD
	1月 2017年	2.4 X	4WD
			内装 B

車種	年	月	ソフト	AT	SR	AW	PS	PV
走行	78,622	2016	冷房	AAC	カワ	TV	7B	2PB
外装色	色別	カラー	※車検時 ※車検時	無	セールスポイント			
内装色	黒	202	※車検時 ※車検時	無	★純正×EVTC			
燃料	ガソリン	軽油	※車検時 ※車検時	無	★ETC ★N-700V			
輸入車	輸入車	輸入車	※車検時 ※車検時	無	★ナビ ★XTRAC			
輸入年	ディーラー	銀行	左	右	月	日	★HID A-Fライ	

リサイクル 預託金	18,900 円	※車検時 8 人	登録地	登録年	登録月	登録日
○注意事項 (車検 不具合部等および状態等)	★床板傷 ★扉板傷 ★ドアガラス割れ					

○検査員報告 (USS使用欄)
シートカバー取付
ルーム内準法規、パネル取付
R250ノット
小キズ
クレンジヤズ



【荷台内寸】約 x x (cm)
長さ 486 cm 幅 184 cm 高さ 190 cm (※車検証上の寸法)



¹ Chassis number – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

² Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped

Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

³ Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

⁴ Use in the contaminated regions – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

⁵ Radioactive contamination test – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

⁶ Japan New Car Assessment Program – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

⁷ Braking Performance Tests – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2023 Car VX Limited. All rights reserved.