



# Vehicle History Report

## VEHICLE DETAILS

**Chassis number <sup>1</sup>:** TE52-015177

**Manufacture date:** 2011-08

**Make:** NISSAN

**Model:** ELGRAND

**Body:** DBA-TE52

**Grade:** 250 HIGHWAY STAR

**Engine:** QR25DE

**Drive:** 2WD

**Transmission:** AT

**Title information <sup>2</sup>:**  **Registered** 

**Accident / Repair:**  **No problem** 

**Odometer rollback:**  **No problem** 

**Manufacturer recall:**  **No problem** 

**Safety grade <sup>3</sup>:**  **★★★★★** 

**Contamination risk:**  **No problem** 

**This vehicle does not qualify for Buyback Guarantee**



Unfortunately, this vehicle does not qualify for our Buyback Guarantee program.

[About Buyback Guarantee](#)

**Average Market Price**



**¥570,000**

This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2023-07-14 05:32:49. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD . Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

## ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

## ODOMETER READINGS HISTORY

Date reported	Data source	Odometer reading (Km)
2020-08-04	MLIT	60400
2022-08-30	MLIT	90400
2023-06-30	MIRIVE Aichi	102510
2023-07-06	JU Aichi	102518

## USE HISTORY

<b>Use in the contaminated regions</b> <sup>4</sup>	<b>Radioactive contamination test fail</b> <sup>5</sup>	<b>Commercial use</b>
Not reported	Not reported	Not reported

## DETAILED HISTORY

Event date	Location	Odometer reading (Km)	Data source	Details
2011-08			NISSAN	Manufactured
2011-08			MLIT	First registration
2020-08-04		60400	MLIT	Inspection
2022-08-30	Shiga	90400	MLIT	Inspection

2023-05-30	Shiga		MLIT	Last registration
2023-06-30	Aichi	102510	MIRIVE Aichi	Auctioned
2023-07-06	Aichi	102518	JU Aichi	Auctioned

## MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
---------------	-------------	---------------	---------

 Not reported



## VEHICLE ASSESSMENT <sup>6</sup>

### Overall Collision Safety Ratings

Driver's seat			Front passenger's seat		
Points	Evaluation	Goal average	Points	Evaluation	Goal average
35.37	★★★★★★	98%	23.33	★★★★★★	97%

\* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

### Braking performance tests <sup>7</sup>

Dry road		40.5 m
Wet road		43.4 m

## VEHICLE SPECIFICATION

<b>1st gear ratio</b>	2.349 ~ 0.394( MANUAL MODE ATTACHING)	<b>2nd gear ratio</b>	-
<b>3rd gear ratio</b>	-	<b>4th gear ratio</b>	-
<b>5th gear ratio</b>	-	<b>6th gear ratio</b>	-

<b>Additional notes</b>	-	<b>Airbag position, capacity</b>	-
<b>Body rear overhang</b>	1020	<b>Body type</b>	MV&1BOX
<b>Chassis number embossing position</b>	FRONT FLOOR PANEL RIGHT SIDE	<b>Classification code</b>	0009
<b>Cylinders</b>	4	<b>Displacement</b>	2480
<b>Electric engine type</b>	-	<b>Electric engine maximum output</b>	-
<b>Electric engine maximum torque</b>	-	<b>Electric engine power</b>	-
<b>Engine maximum power</b>	125/5600( NET)	<b>Engine maximum torque</b>	245/3900( NET)
<b>Engine model</b>	QR25DE	<b>Frame type</b>	SOLID STRUCTURE
<b>Front shaft weight</b>	1040	<b>Front shock absorber type</b>	
<b>Front stabilizer type</b>	TORSION BAR TYPE	<b>Front tires size</b>	225/55R18 98V
<b>Front tread</b>	1.600	<b>Fuel consumption</b>	11.6
<b>Fuel tank equipment</b>	73	<b>Grade</b>	250 HIGHWAY STAR
<b>Height</b>	1.815	<b>Length</b>	4.915
<b>Main brakes type</b>	HYDRAULIC TYPE, FRONT: DISK BACK: DISK	<b>Make</b>	NISSAN
<b>Maximum speed</b>	180(推定)	<b>Minimum ground clearance</b>	0.150
<b>Minimum turning radius</b>	5.7	<b>Model</b>	ELGRAND
<b>Model code</b>	DBA-TE52	<b>Mufflers number</b>	
<b>Rear shaft weight</b>	890	<b>Rear shock absorber type</b>	
<b>Rear stabilizer type</b>	TORSION BAR TYPE -	<b>Rear tires size</b>	225/55R18 98V
<b>Rear tread</b>	1.600	<b>Reverse ratio</b>	1.750
<b>Riding capacity</b>	7	<b>Side brakes type</b>	MACHINE CAR WHEEL制動 SHAPE( DRUM TYPE)
<b>Specification code</b>	16576	<b>Stopping distance</b>	50(100)
<b>Transmission type</b>	AT	<b>Weight</b>	1930

Wheel alignment	2WD	Wheelbase	3.000
Width	1.850		

## AUCTION DATA

**Date: 2023-06-30, Auction: MIRIVE Aichi, Lot #: 70483**

Date:	2023-06-30	Lot #:	70483
Auction name:	MIRIVE Aichi	Region:	Aichi
Make:	NISSAN	Model:	ELGRAND
Reg. year:	2011	Mileage (km):	102510
Displacement (cc):	2500	Transmission:	AT
Color:	PURPLE	Model code:	TE52
Result:	sold	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

**Date: 2023-07-06, Auction: JU Aichi, Lot #: 3141**

Date:	2023-07-06	Lot #:	3141
Auction name:	<a href="#">JU Aichi</a>	Region:	Aichi
Make:	NISSAN	Model:	ELGRAND
Reg. year:	2011	Mileage (km):	102518
Displacement (cc):	2500	Transmission:	AT
Color:	PURPLE	Model code:	TE52
Result:	sold	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

## PHOTOS AND AUCTION SHEETS

# MIRIVE 出品票

[149]

70483

愛知

初年度登録		車名		ドア	グレード	駆動	評価点																						
H23 8		エルブランド			ハイウェイスター	2WD 4WD	4																						
西暦	車年	型式	排気量	保証書	定員																								
2011	2011	DBA - TE52	2,500	有・無	7																								
走行 S#		車検	色 (Col.No)	燃料		外装	内装																						
1 0 2 5 1 0 <small>マイル</small> km		6 8 年 月	パープル LAE	◎・D・電気 (その他)		C	C																						
シフト	エアコン	リサイクル預託金	純正装備品																										
AT	AAC	16,190 円	PS	PW	AW	エアB	ABS	革	SR	ナビ	DTV																		
<b>&lt;注意事項&gt;</b>		<b>名義期限</b>		<b>&lt;セールスポイント&gt;</b>																									
※後送品有り※		月 日		★ユーザー買取車★																									
		輸入車		★ナビ★																									
		ディーラー・並行		★アラウンドビューモニター★																									
		左H・右H		★ドラレコ・HIDヘッドライト★																									
				★純正18インチAW★																									
<b>&lt;検査員記入欄&gt;</b>																													
Fガラス (キズ・崩れ・ヒビ・リペア跡・X要)																													
内装 (キズ・スレ・汚れ・シミ・コゲ・穴・キレ・破れ・割れ)																													
オーディオ (無し・穴) / タイヤ (スタッドレス)																													
<div style="border: 1px solid black; padding: 5px; display: inline-block;"> <p>★ Car Wash ★</p> <p>内装 B・外装 B</p> <p>施工済</p> </div>																													
						<p>キーロック</p> <p>ホイール・CPキズワレ / ドアミラーキズワレ 小キズあり 小ヒビあり 補修有</p>																							
<table border="1"> <tr> <td>数値</td> <td>◎</td> <td>◎</td> <td>◎</td> <td>◎</td> <td>◎</td> </tr> <tr> <td>項目</td> <td>ナビ</td> <td>ビデオ</td> <td>CD/DVD</td> <td>S-CAS</td> <td>リモコン</td> </tr> <tr> <td>品名</td> <td>ナンバー</td> <td>スペアキー</td> <td>キーレス</td> <td>スマートキー</td> <td></td> </tr> </table>				数値	◎	◎	◎	◎	◎	項目	ナビ	ビデオ	CD/DVD	S-CAS	リモコン	品名	ナンバー	スペアキー	キーレス	スマートキー		数量番号 滋賀 301 ほ 1184				車台番号 015177			
数値	◎	◎	◎	◎	◎																								
項目	ナビ	ビデオ	CD/DVD	S-CAS	リモコン																								
品名	ナンバー	スペアキー	キーレス	スマートキー																									







出品番号 [2019] 03141	初度登録年月 23 8 月	車名・グレード エルグランド 250ハイウェイスター	2WD 4WD	評価点 4
型式 DBA-TE52	排気量 2500 CC	ドア 5 形状 W	定員 7 人 積載 kg	ディーラー・並行 モデル 年 式 ハンドル 左・右
車歴 自家用・( )		シフト IAT	セールスポイント(正常に機能するものに限ります)	
車検 R 6 年 8 月(29 日)		冷房 AAC	◎プッシュスタート インテリジェントキー×2(車内)	
受検形態 車検付きのみ記入して下さい ( )		燃料 ガソリン 軽油 ( )	◎純正ナビ・フルセグTV・バックカメラ	
走行 10万2千518 km			◎アラウンドビューモニター ◎HIDヘッドライト	
色 パープル 色替 色コード LAE			装備品(純正品に限り○をつけてください) PS SR PW TE APB TV AW カウシート 新車保証書 有・無	
R券 16,190 円		名変期限 7月31日		

注意事項申告欄(不具合内容等は具体的に記入して下さい)

◎パワースライドドア ◎ドラレコ ◎ビルトインETC

◎AC100V ◎ソナー

修復歴 有 (箇所 )

検査員 FW キズ・~~ヒビ割~~・ヒビ割・リペア跡・X要


記入欄 内装 ~~キズ~~・~~ヒビ割~~・コゲ・穴・~~キレ~~・キレ・破レ

シート フケ ヲキ

A/W 汚

ボデー - AV

後日誌



車台番号 TE52-015177

登録番号 滋賀 301 ぽ 1184

A-キズ E-エウボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済

形式指定番号	類別区分番号
車庫証明用 長さ cm	高さ cm


**JU愛知初出品** ※3ヶ月以内のJU愛知出品歴がありません

**JU 愛知**



**JU 愛知**









**1 Chassis number** – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

**2 Title information:**

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped

Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

**3 Determining the overall collision safety performance evaluation** – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

**4 Use in the contaminated regions** – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

**5 Radioactive contamination test** – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

**6 Japan New Car Assessment Program** – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

**7 Braking Performance Tests** – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2023 Car VX Limited. All rights reserved.