

VEHICLE DETAILS

Chassis number ¹: PE52-041530

Manufacture date: 2013-09

Make: NISSAN

Model: ELGRAND

Body: DBA-PE52

Grade: HIGHWAY STAR

Engine: VQ35DE

Drive: 2WD

Transmission: AT

Title information ²:



Registered



Accident / Repair:



No problem



Odometer rollback:



No problem



Manufacturer recall:



No problem



Safety grade ³:



★★★★★



Contamination risk:



No problem



This vehicle does not qualify for Buyback Guarantee

Average Market Price



Unfortunately, this vehicle does not qualify for our Buyback Guarantee program.

[About Buyback Guarantee](#)



¥0

This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2023-09-01 00:41:18. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD . Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

ODOMETER READINGS HISTORY

Date reported	Data source	Odometer reading (Km)
2020-09-03	MLIT	50000
2022-09-05	MLIT	68900
2023-08-24	MIRIVE Osaka	73510

USE HISTORY


Use in the contaminated regions ⁴	Radioactive contamination test fail ⁵	Commercial use
Not reported	Not reported	Not reported

DETAILED HISTORY

Event date	Location	Odometer reading (Km)	Data source	Details
2013-09			NISSAN	Manufactured
2013-09			MLIT	First registration
2020-09-03		50000	MLIT	Inspection
2022-09-05	Ehime	68900	MLIT	Inspection
2023-06-07	Ehime		MLIT	Last registration

MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
---------------	-------------	---------------	---------

 Not reported


VEHICLE ASSESSMENT ⁶

Overall Collision Safety Ratings

Driver's seat			Front passenger's seat		
Points	Evaluation	Goal average	Points	Evaluation	Goal average
35.37	★★★★★	98%	23.33	★★★★★	97%

* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

Braking performance tests ⁷

Dry road  40.5 m

Wet road  43.4 m

VEHICLE SPECIFICATION

1st gear ratio	2.371 ~ 0.439(MANUAL MODE ATTACHING)	2nd gear ratio	-
3rd gear ratio	-	4th gear ratio	-
5th gear ratio	-	6th gear ratio	-
Additional notes	-	Airbag position, capacity	
Body rear overhang	1020	Body type	MV&1BOX

Chassis number embossing position	FRONT FLOOR PANEL RIGHT SIDE	Classification code	0135
Cylinders	V6 WIDTH	Displacement	3490
Electric engine type	-	Electric engine maximum output	-
Electric engine maximum torque	-	Electric engine power	-
Engine maximum power	206/6400(NET)	Engine maximum torque	344/4400(NET)
Engine model	VQ35	Frame type	SOLID STRUCTURE
Front shaft weight	1110	Front shock absorber type	
Front stabilizer type	TORSION BAR TYPE	Front tires size	225/55R18 98V
Front tread	1.600	Fuel consumption	-
Fuel tank equipment	73	Grade	HIGHWAY STAR
Height	1.815	Length	4.915
Main brakes type	HYDRAULIC TYPE, FRONT: DISK BACK: DISK	Make	NISSAN
Maximum speed	180(推定)	Minimum ground clearance	0.150
Minimum turning radius	5.4 5.7	Model	ELGRAND
Model code	DBA-PE52	Mufflers number	
Rear shaft weight	920	Rear shock absorber type	
Rear stabilizer type	TORSION BAR TYPE -	Rear tires size	225/55R18 98V
Rear tread	1.600	Reverse ratio	1.766
Riding capacity	7	Side brakes type	MACHINE CAR WHEEL制動SHAPE(DRUM TYPE)
Specification code	16578	Stopping distance	50(100)
Transmission type	AT	Weight	2030
Wheel alignment	2WD	Wheelbase	3.000
Width	1.850		

AUCTION DATA


Date: 2023-08-24, Auction: MIRIVE Osaka, Lot #: 70102

Date:	2023-08-24	Lot #:	70102
Auction name:	MIRIVE Osaka	Region:	Osaka
Make:	NISSAN	Model:	ELGRAND
Reg. year:	2013	Mileage (km):	73510
Displacement (cc):	3500	Transmission:	AT
Color:	PURPLE	Model code:	PE52
Result:	sold	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

PHOTOS AND AUCTION SHEETS

MIRIVE 出品票

[1892]
70102
大阪

初度登録	車名	ドア	グレード	駆動	評価点
H25 9 年 月	エルブランド	5	ハイウェイスター	2WD 4WD	4
年 月	型式	排気量	保証年	定価	
2013	DBA - PE52	3,500 cc	有 無	7	
走行	S#	車種	色 (ColNo)	燃料	外装
73 6510 km		6 9 年 月	パープル LAE	◎・D・電気 (その他)	内装
シフト	エアコン	リサイクル積込	純正装備品		
IAT	AAC	16,090 円	PS PW AW	エアB ABS	革 SR ナビ DTV
<注意事項>		<セールスポイント>			
★社外HDDナビ・フルセグTV!		★サンルーフ!!			
★バックカメラ!!		★パワーバックドア!!			
		★両側パワースライドドア!!			
		★HIDヘッドライト!! ETC!!			
		★ブラックレザー調シート付!!			
<検査員記入欄>		キーロック			
Fガラス (キズ・割石・ヒビ・リペア跡・X要)		ホイール・CPキズワレノドアミラーキズワレ			
内装 (キズ・スリ・汚れ・シミ・コゲ・穴・キレ・破れ・割れ)		小キズ等小し有補修有			
オーディオ (無し・穴) / タイヤ (スタッドレス)					
スマートキー車内					
Ac可 ナビ付					
販売店	ナビ取付	ロム/SD	B-CAS	リモコン	登録番号
ナンバー	スピーカー	キーレス	スマートキ		愛媛 330 や 6611
					車台番号
					041530









¹ Chassis number – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

² Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped

Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

³ Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

⁴ Use in the contaminated regions – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

⁵ Radioactive contamination test – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

⁶ Japan New Car Assessment Program – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

⁷ Braking Performance Tests – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2023 Car VX Limited. All rights reserved.